

**Adjuster Letter/DV not verified.**  
**This claim is to be authorized on the insurer's behalf.**  
**Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.**  
**Click on 'View Letter/DV' to verify the offer.**

**You cannot authorize this offer because**  
**Adjuster Letter/DV not verified.**  
**File to be authorized by your superior.**

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22010288/EVY3E2

**Date:** 25/10/2022

### REFERENCE

Insured/Claimant:	LIM KIM MOOI	Policy No:	DMPG22007098	
Date of Loss:	13/10/2022	Nature of Claim:	OD	Claim No: CDMPG22002155

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT8610B		
Make & Model:	BMW 528I, 2.0 AT ABS D/AB SR NAV HID (A)	Engine No:	B1710894N20B20A
Reg. Date:	29/05/2015 (Man. Year: 2015)	Chassis No:	WBA5A52070D823656
Colour:	Brown	Odometer:	165213 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,956.40	3,943.30	3,013.10	43.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,793.00	6,484.00	3,309.00	33.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>16,749.40</b>	<b>10,427.30</b>	<b>6,322.10</b>	<b>37.75</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,172.46	729.91	442.55	37.75
<b>Nett Amount (\$\$)</b>	<b>17,921.86</b>	<b>11,157.21</b>	<b>6,764.65</b>	<b>37.75</b>

### INSPECTION

Date of Assignment:	17/10/2022		
Date Inspected:	17/10/2022	Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2022)
Parts:	143	BMW 528I 2.0 AT ABS D/AB SR NAV HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT8610B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*RADIATOR UPPER SEALING	* Check	34.80 FS	*- FS
3	1		*RADIATOR	* Check	836.85 FS	*- FS
4	1		*BONNET	Dented	1,312.90 FS	*1,312.90 FS
5	1		*FRT BUMPER TOP CARRIER	* Check	419.45 FS	*- FS
6	1		*OPEN GRID, R	* Check	76.95 FS	*- FS
7	1		*LH FINISHER ROD (BASIS)	* Check	33.55 FS	*- FS
8	1		*RH FINISHER ROD (BASIS)	* Check	33.55 FS	*- FS
9	1		*BRACKET HEADLIGHT RH	* Check	15.00 FS	*- FS
10	1		*SUPPORT CENTRAL	* Check	14.15 FS	*- FS
11	1		*MOUNTING SUPPORT	* Check	15.75 FS	*- FS
12	1		*PANEL (BUMPER FRT)	Dented	1,106.35 FS	*1,106.35 FS
13	1		*FLAP TOWING EYE PRIMED	* Check	44.35 FS	*- FS
14	1		*GRILLE, FRON (RH)	Broken	131.20 FS	*131.20 FS
15	1		*GRILLE, FRON (LH)	* Check	131.20 FS	*- FS
16	1		*FRONT PANEL V STRUT	* Check	120.75 FS	*- FS
17	1		*SUPPORT RH	* Check	129.25 FS	*- FS
18	10		*C CLIP NUT	Necessary	13.50 FS	*13.50 FS
19	1		*AIR DUCT RADIATOR	Broken	189.40 FS	*189.40 FS
20	1		*PLAQUE 82MM	* Check	72.85 FS	*- FS
21	1		*HEADLIGHT (RH)	Broken	1,109.95 FS	*1,109.95 FS
22	1		*CONDENSER AL	* Check	1,034.65 FS	*- FS
Total Parts (S\$)					6,956.40	3,943.30

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE BONNET, FRONT SUPPORT, FRONT BUMPER, MAKE GOOD FRONT RHS FENDER AND ATTACHMENTS	New	3,825.00	2,550.00
2	TO RESPRAY BONNET, FRONT BUMPER, FRONT RHS FENDER AND AFFECTED AREAS	New	3,221.00	3,059.00
3	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL	New	177.00	168.00
5	TO SUPPLY FRONT EMBOSS NUMBER PLATE	New	83.00	83.00
6	TO REPLACE RIGHT HEADLAMP	New	481.00	456.00
7	TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM AND CONDUCT CHECK FOR LEAK (ALL MODELS EXCEPT 7 SERIES) (* Check)	New	826.00	0.00
8	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING VACUUM SYSTEM, TOP UP FREON GAS AND CONDUCT CHECK FOR LEAK (FOR ALL MODELS EXCEPT FOR 7 SERIES) (* Check)	New	1,003.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>9,793.00</b>	<b>6,484.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >