

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI22010289/UVY3Q2**Date:** 09/11/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SMZ9150A **Insured Vehicle No :** YQ4061L
 Date of Loss: 10/10/2022 Nature of Claim: TP Claim No: CDMCG22002161

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ9150A**
 Make & Model: MAZDA 5, 2.0 5 DR WAGON (A) Engine No: PE10427717
 Reg. Date: 17/02/2017 (Man. Year: 2016) Chassis No: JM6CW1071G0125033
 Colour: Grey Odometer: 90500 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm
 Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,714.80	6,678.00	10,036.80	60.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	1,860.00	2,770.00	59.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,344.80	8,538.00	12,806.80	60.00
Approved Total (Overridden) (S\$)		6,800.00		
Nett Amount (S\$)	21,344.80	6,800.00	14,544.80	68.14

INSPECTION

Date of Assignment: 17/10/2022
 Date Inspected: 17/10/2022 Inspected At: 2ND Auto Pte Ltd (HQ)
 15 Kaki Bukit Road 4, #01-05/53 Bartley Biz
 Centre
 Singapore 417808
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Nov 2022)	
Parts:	N/A	MAZDA 5 2.0 5 DR WAGON (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ9150A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Distorted	1,283.00 FL	*1,108.20 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	383.00 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Cracked	133.00 FL	*133.00 FL
4	2		*FRONT BUMPER BRACKET	Not Necessary	177.00 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Twisted	192.00 FL	*165.10 FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	67.00 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	197.00 FL	*- FL
8	1		*FRONT BUMPER CENTER LOGO	Necessary	68.00 FL	*68.00 FL
9	1		*FRONT BUMPER LOWER LIP	No such part	380.00 FL	*- FL
10	1		*FRONT LEFT FOG LAMP	Not Necessary	260.00 FL	*- FL
11	1		*FRONT RIGHT FOG LAMP	Not Necessary	260.00 FL	*- FL
12	1		*FRONT LEFT FOG LAMP GARNISH	Not Necessary	105.00 FL	*- FL
13	1		*FRONT RIGHT FOG LAMP GARNISH	Torn	105.00 FL	*105.00 FL
14	1		*FRONT HORN	Not Necessary	108.00 FL	*- FL
15	1		*FRONT GRILLE ASSY	Cracked	267.00 FL	*267.00 FL
16	1		*FRONT BONNET ASSY	Distorted	1,421.00 FL	*1,085.60 FL
17	2		*FRONT BONNET RUBBER STOPPER	Not Necessary	26.00 FL	*- FL
18	2		*FRONT BONNET HINGES	Bent / Twisted	120.00 FL	*120.00 FL
19	1		*FRONT BONNET LOCK MECHANISM	Twisted	180.00 FL	*166.80 FL
20	1		*FRONT BONNET LOCK CATCH	Not Necessary	80.00 FL	*- FL
21	1		*FRONT BONNET RUBBER SEAL	Not Necessary	88.00 FL	*- FL
22	1		*FRONT BONNET STAND	Not Necessary	158.00 FL	*- FL
23	1		*FRONT BONNET INSULATION	Not Necessary	218.00 FL	*- FL
24	1		*FRONT LEFT HEADLAMP	Not Necessary	887.00 FL	*- FL
25	1		*FRONT RIGHT HEADLAMP	Broken	887.00 FL	*887.00 FL
26	1		*FRONT LEFT HEADLAMP INNER BRACKET	No such part	95.00 FL	*- FL
27	1		*FRONT RIGHT HEADLAMP INNER BRACKET	No such part	95.00 FL	*- FL
28	1		*FRONT ENGINE LOWER COVER	Torn	380.00 FL	*281.50 FL
29	1		*FRONT AIR DUCT ASSY	Not Necessary	192.00 FL	*- FL
30	1		*FRONT AIR INTAKE BOX	Not Necessary	264.00 FL	*- FL
31	1		*FRONT AIR INTAKE HOSE	Not Necessary	109.00 FL	*- FL
32	1		*FRONT WIPER TANK	Distorted	106.00 FL	*106.00 FL
33	1		*FRONT WIPER TOP GARNISH	Torn	415.00 FL	*415.00 FL
34	1		*FRONT WIPER BLADE ASSY	Not Necessary	160.00 FL	*- FL
35	1		*FRONT LEFT ENGINE MOUNTING	Not Necessary	280.00 FL	*- FL
36	1		*FRONT RIGHT ENGINE MOUNTING	Not Necessary	280.00 FL	*- FL
37	1		*FRONT SUPPORT PANLE ASSY	Cracked	1,163.00 FL	*451.20 FL
38	4		*FRONT SUPPORT PANLE RUBBER STOPPER	Not Necessary	66.00 FL	*- FL
39	1		*FRONT RADIATOR ASSY	Not Necessary	1,121.00 FL	*- FL
40	1		*FRONT RADIATOR TOP HOSE	Not Necessary	126.00 FL	*- FL
41	1		*FRONT RADIATOR BOTTOM HOSE	Not Necessary	124.00 FL	*- FL
42	1		*FRONT COOLING FAN ASSY WITH MOTOR COMPLETE ASSY	Not Necessary	881.00 FL	*- FL
43	1		*FRONT AIR-CON CONDENSER	Not Necessary	1,041.00 FL	*- FL
44	1		*FRONT AIR-CON SUCTION PIPE	Not Necessary	197.00 FL	*- FL
45	1		*FRONT AIR-CON DISCHARGE PIPE	Not Necessary	197.00 FL	*- FL
46	1		*FRONT LEFT FENDER	Repair	792.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT LEFT FENDER INNER COWLING	Not Necessary	208.00 FL	*- FL
48	1		*FRONT RIGHT FENDER	Distorted	792.00 FL	*566.10 FL
49	1		*FRONT RIGHT FENDER INNER COWLING	Torn	208.00 FL	*208.00 FL
50	1		*FRONT KNUCKLE ARM O/S	Bent	392.00 FL	*392.00 FL
51	1		*FRT KNUCKLE ARM BEARING O/S	Necessary	165.00 FL	*165.00 FL
52	1		*FRT LOWER ARM O/S	Bent	408.00 FL	*408.00 FL
53	1		*FRT SHOCK ABSORBER O/S	Bent	399.00 FL	*399.00 FL
54	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*50.00 FS
55	4		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
56	6		*FRONT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
57	1		*FRONT AIR CON GAS	Not Necessary	100.00 FS	*- FS
58	2		*FRONT RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
59	1		*SET FRONT ENGINE LOWER COVER CLIPS	Necessary	40.00 FS	*40.00 FS
60	1		*FRONT RIGHT WHEEL RIM	Bent / Warped	750.00 FS	*500.00 FS
61	1		*FRONT RIGHT TYRE	Serviceable	400.00 FS	*- FS
62	1		*SET FRONT BONNET INSULATION CLIPS	Necessary	50.00 FS	*50.00 FS
63	6		*FRONT LEFT FENDER INNER COWLING CLIPS	Not Necessary	40.00 FS	*- FS
64	1		*SET FRONT RIGHT FENDER INNER COWLING CLIPS	Necessary	40.00 FS	*40.00 FS
65	1		*FRONT NO PLATE	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,456.00	8,177.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,741.20	1,499.50
Total Parts (\$\$)	16,714.80	6,678.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN FRONT AFFECTED AREA AND REPLACED FRONT DAMAGED PARTS	New	1,600.00	800.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	1,600.00	800.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	20.00
4	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM	New	80.00	0.00
5	TO REMOVE AND INSTALL AIR CON SYSTEM TO FACILITATE THE REPAIR AND REFILL GAS	New	180.00	100.00
6	TO REMOVE AND INSTALL COOLING SYSTEM TO FACILITATE THE REPAIR AND CHECK FOR LEAKAGE	New	180.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
8	TO BALANCE FRONT RIGHT WHEEL	New	50.00	0.00
9	TO REPAIR STRAIGHTEN AND ALIGN FRONT RIGHT DOOR	New	180.00	0.00
10	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	0.00
11	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	140.00	60.00
12	TOWING SERVICE	New	100.00	0.00
Gross Labour Cost (\$\$)			4,630.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >