

Vehicle Damage Assessment Report for [SMZ9150A]

Estimate Created: 07/11/2022 00:08 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 07/11/2022 00:26 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mazda	Model	5
Engine Type			
License Plate Number	SMZ9150A	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$6800.00 with 6 days for repair

Insurlogic 1 (07/11/2022 00:26)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER		1	1108.20	-20.00 %	886.56
FRONT BUMPER RETAINER		1	133.00	-20.00 %	106.40
FRONT BUMPER LOWER GRILLE		1	165.10	-20.00 %	132.08
FRONT BUMPER CTR LOGO		1	68.00	-20.00 %	54.40
FRONT FOG LAMP GARNISH		1	105.00	-20.00 %	84.00
FRONT GRILLE ASSY		1	267.00	-20.00 %	213.60
BONNET ASSY		1	1085.60	-20.00 %	868.48
BONNET HINGES		1	120.00	-20.00 %	96.00
FRONT BONNET LOCK MECHNISM		1	166.80	-20.00 %	133.44
HEADLAMP RH		1	887.00	-20.00 %	709.60
ENGINE LOWER COVER		1	281.50	-20.00 %	225.20
FRONT WIPER TANK		1	106.00	-20.00 %	84.80
FRONT WIPER TOP GARNISH		1	415.00	-20.00 %	332.00
FRONT SUPPORT PANEL ASSY		1	451.20	-20.00 %	360.96
FRONT FENDER RH		1	566.10	-20.00 %	452.88
FRONT FENDER INNER COWLING		1	208.00	-20.00 %	166.40
FRONT KUNCKLE RH		1	392.00	-20.00 %	313.60
FRONT KUNCKLE ARM BEARING RH		1	165.00	-20.00 %	132.00
FRONT LOWER ARM RH		1	408.00	-20.00 %	326.40
FRONT SHOCK ABSORBER RH		1	399.00	-20.00 %	319.20

Parts Subtotal 5,998.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER CLIPS		1.0	50.00	0.00 %	50.00
FRONT ENGINE LOWER COVER CLIPS		1.0	40.00	0.00 %	40.00
FRONT WHEEL RIM		1.0	500.00	0.00 %	500.00
BONNET INSULATION CLIPS		1.0	50.00	0.00 %	50.00

FRONT FENDER INNER COWLING CLIPS	1.0	40.00	0.00 %	40.00
----------------------------------------	-----	-------	--------	-------

Materials Subtotal 680.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREA	RnR	800.00	0.00 %	800.00
CHECK WIRING	RnR	20.00	0.00 %	20.00
RNR AIRCON SYSTEM AND REFILL AIRCON GAS	RnR	100.00	0.00 %	100.00
WHEEL ALIGNMENT	RnR	80.00	0.00 %	80.00
ANTI RUST	RnR	60.00	0.00 %	60.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ACCIDENT AFFECTED AREA	Full spray	800.00	0.00 %	800.00

General Labor Subtotal 1,060.00

Paint Labor Subtotal 800.00

Labor Subtotal 1,860.00

Summary

Repair Cost 8,538.00

Discount(20 %) (1,738.00)

6,800.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 6,800.00