

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22010291/UVY3E2**Date:** 09/11/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001607366
Claimant Vehicle No :	SLB6670Z	Insured Vehicle No :	GBK9072B
Date of Loss:	14/10/2022	Nature of Claim:	TP
		Claim No:	287735

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB6670Z	Engine No:	D4162T2695701
Make & Model:	VOLVO S60, 1.6 D2 (A)	Chassis No:	YV1FS84ABE2300980
Reg. Date:	27/05/2014 (Man. Year: 2013)	Odometer:	228127 km
Colour:	Grey		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,745.90	2,571.30	9,174.60	78.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,210.00	2,580.00	68.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,535.90	3,781.30	11,754.60	75.66
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	15,535.90	3,000.00	12,535.90	80.69

INSPECTION

Date of Assignment:	18/10/2022	
Date Inspected:	17/10/2022	Inspected At: Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339 Singapore 470130
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2022)
Parts:	143	VOLVO S60 1.6 D2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB6670Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	3,100.00 FL	*- FL
2	1		*REAR BOOT INNER LOCK	Not Necessary	426.00 FL	*- FL
3	1		*REAR BOOT WEATHERSTRIP	Not Necessary	189.00 FL	*- FL
4	1		*REAR BOOT VOLVO EMBLEM	Not Necessary	135.00 FL	*- FL
5	2		*REAR TAILLAMPS	Not Necessary	1,516.00 FL	*- FL
6	1		*REAR END PANEL	Repair	1,185.00 FL	*- FL
7	1		*REAR END PANEL INNER GARNISH	Not Necessary	345.00 FL	*- FL
8	1		*REAR BUMPER	Deformed / Torn	1,960.00 FL	*1,842.00 FL
9	2		*REAR BUMPER SIDE BRACKETS	Not Necessary	192.00 FL	*- FL
10	1		*REAR BUMPER BEAM	Not Necessary	116.00 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Repair	1,170.00 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	180.00 FL	*- FL
13	2		*REAR BUMPER PDC SENSORS -SIDE	Not Necessary	440.00 FL	*- FL
14	2		*REAR BUMPER PDC SENSORS-LOWER	Shorted	624.00 FL	*410.00 FL
15	1		*REAR BUMPER LOWER DIFFUSER	Deformed	885.00 FL	*605.00 FL
16	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	72.00 FL	*- FL
17	1		*REAR EXHAUST CHROME TAIL PIPE	Repair	516.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	13,051.00	2,857.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,305.10	285.70
Total Parts (S\$)	11,745.90	2,571.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
5	TO APPLY UNDERCOATING	New	200.00	0.00
6	PANEL BEATING	New	1,600.00	480.00
7	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,790.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >