

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22010294/GQY3Q2**Date:** 25/04/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : FBT4085A **Insured Vehicle No :** EJ37H

Date of Loss: 03/10/2022 Nature of Claim: TP Claim No: DMPC2200454H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBT4085A**

Make & Model: YAMAHA SPARK, 135cc Engine No: 5YP007112

Reg. Date: 29/12/2006 (Man. Year: 2006) Chassis No: 5YP007112

Colour: Black Odometer: 79706 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 70/90-17

Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,338.50	3,001.10	1,337.40	30.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	400.00	800.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,538.50	3,401.10	2,137.40	38.59
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	5,538.50	2,700.00	2,838.50	51.25

INSPECTION

Date of Assignment: 17/10/2022

Date Inspected: 18/10/2022 Inspected At: 25 KAKI BUKIT ROAD 4
#03-94 SYNERGY @ KB
SINGAPORE 417800
Repairer: Pro-jex V2d Motor Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Apr 2023)	
Parts:	N/A	YAMAHA SPARK 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBT4085A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	150.00 FL	*150.00 FL
2	1		*FRONT RIM	Distorted	380.00 FL	*380.00 FL
3	1		*FRONT RIM BEARING	Necessary	75.00 FL	*50.00 FL
4	1		*FRONT RIM BEARING SHAFT/BOLT	Bent	45.00 FL	*45.00 FL
5	1		*FRONT BRAKE DISC	Distorted	330.00 FL	*230.00 FL
6	2		*FRONT FORKS	Bent	800.00 FL	*800.00 FL
7	1		*FRONT FORKS STEM	Not Necessary	175.00 FL	*- FL
8	1		*FRONT FORKS STEM BEARING	Necessary	85.00 FL	*85.00 FL
9	1		*FRONT FORK UPPER BRACKET	Distorted	115.00 FL	*115.00 FL
10	1		*FRONT BRAKE HOSE	Not Necessary	75.00 FL	*- FL
11	2		*FRONT SIGNAL LAMPS	Cracked	130.00 FL	*130.00 FL
12	1		*FRONT SIGNAL LAMPS COWLING	Cracked	107.00 FL	*107.00 FL
13	1		*FRONT SIGNAL LAMPS COWLING BRACKET	Not Necessary	65.00 FL	*- FL
14	1		*HEADLAMP	Cracked	282.50 FL	*282.50 FL
15	1		*HEADLAMP COVER (OUTER)	Cut	115.00 FL	*90.00 FL
16	1		*HEADLAMP COVER (INNER)	Cracked	125.00 FL	*125.00 FL
17	1		*HANDLE BAR	Bent	145.00 FL	*120.00 FL
18	1		*SET HANDLE BAR GRIP	Not Necessary	55.00 FL	*- FL
19	2		*FRONT TOP SIDE GARNISH	Not Necessary	150.00 FL	*- FL
20	2		*FRONT TOP SIDE GARNISH (INNER)	Not Necessary	130.00 FL	*- FL
21	2		*FRONT LOWER SIDE GARNISH	Not Necessary	160.00 FL	*- FL
22	1		*FRONT LOWER SIDE GARNISH (INNER)	Not Necessary	78.00 FL	*- FL
23	1		*FRONT LOWER CENTRE GARNISH	Cracked	75.00 FL	*75.00 FL
24	1		*FRONT TOP CENTRE GARNISH	Cracked	56.00 FL	*56.00 FL
25	1		*GEAR LEVER	Not Necessary	68.00 FL	*- FL
26	1		*FRONT FOOTREST	Scratched	40.00 FL	*40.00 FL
27	1		*FRONT FOOTREST BRACKET	Dented	85.00 FL	*85.00 FL
28	1		*FULL STAND	Not Necessary	135.00 FL	*- FL
29	1		*SIDE STAND	Not Necessary	95.00 FL	*- FL
30	1		*REAR LH FOOTREST PEG/RUBBER	Scratched	35.00 FL	*35.00 FL
31	1		*REAR LH FOOTREST BRACKET	Not Necessary	125.00 FL	*- FL
32	1		*MIDDLE CENTER GARNISH (IN FRONT OF FRONT SEAT)	Cracked	95.00 FL	*95.00 FL
33	1		*REAR LH TAILBOARD FAIRING	Cracked	133.50 FL	*133.50 FL
34	1		*FRONT NETTING BASKET	Bent	65.00 FS	*65.00 FS
35	1		*FRONT LICENCE PLATE	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,810.00	3,324.00
- List Item Discount on L Items 10.00/10.00% (\$)	471.50	322.90
Total Parts (\$)	4,338.50	3,001.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	400.00	300.00
2	PAINTING AND STICKERS	New	450.00	100.00
3	CHASSIS ALIGNMENT	New	350.00	0.00
Gross Labour Cost (S\$)			1,200.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >