

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 3533S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE (CONSISTENT)	TO REPAIR SEE LABOUR	913.00	-
1	TAIL GATE WINDSCREEN RUBBER (CONSISTENT)	NOT NECESSARY	164.00	-
1	TAIL GATE WINDSCREEN INNER SEALANT (CONSISTENT)	NOT NECESSARY	120.00	-
1	TAIL GATE WINDSCREEN TAPE FORM (CONSISTENT)	NOT NECESSARY	50.00	-
1	TAIL GATE EMBLEM (CONSISTENT)	NOT NECESSARY	45.00	-
1	TAIL GATE CC PLATE (CONSISTENT)	NOT NECESSARY	25.00	-
1	TAIL GATE MIVCE PLATE (CONSISTENT)	NOT NECESSARY	70.00	-
1	TAIL GATE SPACE STAR PLATE (CONSISTENT)	NOT NECESSARY	58.00	-
1	TAIL GATE WINDSCREEN SUNX STICKER (CONSISTENT)	NOT NECESSARY	300.00	-
2	TAIL LAMP @\$481.00 (CONSISTENT)	CRACKED	962.00	962.00
1	REAR BUMPER (CONSISTENT)	TORN	684.00	684.00
2	REAR BUMPER REFLECTOR @\$40.00 (CONSISTENT)	NOT NECESSARY	80.00	-
2	REAR BUMPER INNER BRACKETS @\$45.00 (CONSISTENT)	BENT	90.00	90.00
1	SET REAR BUMPER INNER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE HOLDERS @\$30.00 (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR PANEL (CONSISTENT)	BADLY DENTED	428.00	428.00
1	REAR BUMPER TOP COVER (CONSISTENT)	TWISTED	120.00	120.00
1	REAR EXHAUST PIPE (CONSISTENT)	NOT NECESSARY	835.00	-
	LESS 10% DISCOUNT		-	-239.40
			5,054.00	2,154.60
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSORS (SN) (CONSISTENT)	SHORTED	350.00	200.00
			350.00	200.00
	<u>LABOUR</u>			
	TO RUSTPROOF .		200.00	30.00
	TO REMOVE/REFIT REAR WINDSCREEN .	NOT NECESSARY	140.00	-
	TO REMOVE /REFIT REAR EXHAUST PIPE .	NOT NECESSARY	100.00	-

Report Ref No. CC4/ASM22010297/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE /REFIT REAR INTERIOR TO EFFECT REPAIR .		100.00	80.00
	TO DISMANTLE /RENEW ACCIDENT PORTION .INCLUSIVE OF THE REPAIR OF TAIL GATE.		1,200.00	900.00
	TO SPRAY PAINT .		1,200.00	900.00
			2,940.00	1,910.00
	GRAND TOTAL		8,344.00	4,264.60

RECOMMENDED COST OF LUMP SUM REPAIRS		3,400.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22010297/Upa3q2

CHUA KANG SENG

Licensed Appraiser