6/16/23, 1:43 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB22010302/TYA3Q2

16/06/2023 Date:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

**Claimant Vehicle** SH6598K Insured Vehicle No: SNC5078L

No:

Date of Loss: 13/10/2022 Nature of Claim: TP Claim No: MFL2022D0006105

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SH6598K

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) 2ZRS062269 Engine No:

Reg. Date: 07/09/2017 (Man. Year: 2017) Chassis No: JTDKB3FUX03563795

Colour: Blue Odometer: 0 km

**Engine Capacity:** 1798 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Rear Left Side: Front Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,075.03	4,320.48	754.55	14.87
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		1,560.00	1,145.00	415.00	26.60
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,646.03	5,476.48	1,169.55	17.60
A	pproved Total (Overridden) (S\$)		4,400.00		
	(S\$)	6,646.03	4,400.00	2,246.03 157.22	33.80
	+ GST 7.00/7.00% (S\$)	465.22	308.00		33.79 33.80
	Nett Amount (S\$)	7,111.25	4,708.00	2,403.25	
	+ Loss of Use (5.5 x S\$	40.00/day) (S\$)	220.00		
	+ Car Rental (5.5 x S\$1	25.40/day) (S\$)	689.70		
	+ Doc/S	Search Fee (S\$)	7.45		
	Ne	ett Liability (S\$)	5,625.15		

**INSPECTION** 

Date of Assignment: 18/10/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive Date Inspected: 17/10/2022 Inspected At:

Singapore 508969

Estimated Period of Repair: 3.0 days

MOHD TAUFIKH BIN HAMID Adjuster: Manager: Ezlyna NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Dec 2022)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH6598K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

Qty Part No.	Particulars	Condition	Repairer's	Amount
1	*FRT BUMPER ASSY	Deformed	586.18 FL	*586.18 FL
10	*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
1	*FRT BUMPER BEAM	Not Necessary	812.89 FL	*- FL
1	*FRT BUMPER SPONGE	Cracked	78.80 FL	*78.80 FL
1	*FRT BUMPER SIDE BRACKET LH	Deformed	90.75 FL	*90.75 FL
1	*FRT FENDER LH	Bent	1,111.93 FL	*1,111.93 FL
1	*FRT FENDER SHIELD LH	Missing	198.50 FL	*198.50 FL
1	*FRT BUMPER TOW COVER LH	Deformed	28.38 FL	*28.38 FL
1	*FRT BUMPER LOWER GRILLE	Not Necessary	193.18 FL	*-FL
1	*FRT FENDER EMBLEM LH	Necessary	86.50 FL	*86.50 FL
1	*HEADLAMP ASSY LH	Cracked	2,637.60 FL	*2,637.60 FL
1	*FRT FOG LAMP ASSY LH	Missing	920.00 FL	*920.00 FL
anchise part. L=ListIte	mDisc.	-		
		Sub Total (S\$)	6,766.71	5,760.64
	- List Item Discount	on L Items 25.00/25.00% (S\$)	1,691.68	1,440.16
		Total Parts (S\$)	5,075.03	4,320.48
	1 10 1 1 1 1 1 1 1 1 1	1 *FRT BUMPER ASSY 10 *FRT BUMPER CLIPS 1 *FRT BUMPER BEAM 1 *FRT BUMPER SPONGE 1 *FRT BUMPER SIDE BRACKET LH 1 *FRT FENDER LH 1 *FRT FENDER SHIELD LH 1 *FRT BUMPER TOW COVER LH 1 *FRT BUMPER LOWER GRILLE 1 *FRT FENDER EMBLEM LH 1 *HEADLAMP ASSY LH 1 *FRT FOG LAMP ASSY LH 2 canchise part. L=ListItemDisc.	1 *FRT BUMPER ASSY Necessary 1 *FRT BUMPER BEAM Not Necessary 1 *FRT BUMPER SPONGE Cracked 1 *FRT BUMPER SIDE BRACKET LH Deformed 1 *FRT FENDER LH Bent 1 *FRT FENDER SHIELD LH Missing 1 *FRT BUMPER TOW COVER LH Deformed 1 *FRT BUMPER TOW GOVER LH Deformed 1 *FRT BUMPER LOWER GRILLE Not Necessary 1 *FRT FENDER EMBLEM LH Necessary 1 *FRT FENDER EMBLEM LH Cracked 1 *FRT FOG LAMP ASSY LH Gracked 1 *FRT FOG LAMP ASSY LH Missing 2 **Cracked** 1 *FRT FOG LAMP ASSY LH Missing 3 **Cracked** 2 **Cracked** 3 **Cracked** 4 **Cracked** 5 **Cracked** 5 **Cracked** 6 **Cracked** 7 **Cracked** 6 **Cracked** 7 **Cracked** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **FRT FOG LAMP ASSY LH Missing** 8 **Cracked** 1 **Cracked** 1 **Cracked** 1 **Cracked** 1 **Cracked** 1 **Cracked** 1 **Cracked** 2 **Cracked** 3 **Cracked** 3 **Cracked** 4 **Cracked** 5 **Cracked** 6 **Cracked** 6 **Cracked** 6 **Cracked** 6 **Cracked** 6 **Cracked** 7 **Cracked** 8 **C	1         *FRT BUMPER ASSY         Deformed         586.18 FL           10         *FRT BUMPER CLIPS         Necessary         22.00 FL           1         *FRT BUMPER BEAM         Not Necessary         812.89 FL           1         *FRT BUMPER SPONGE         Cracked         78.80 FL           1         *FRT BUMPER SIDE BRACKET LH         Deformed         90.75 FL           1         *FRT FENDER LH         Bent         1,111.93 FL           1         *FRT FENDER SHIELD LH         Missing         198.50 FL           1         *FRT BUMPER TOW COVER LH         Deformed         28.38 FL           1         *FRT BUMPER LOWER GRILLE         Not Necessary         193.18 FL           1         *FRT FENDER EMBLEM LH         Necessary         86.50 FL           1         *HEADLAMP ASSY LH         Cracked         2,637.60 FL           1         *FRT FOG LAMP ASSY LH         Missing         920.00 FL           anchise part. L=ListItemDisc.         Sub Total (S\$)         6,766.71           List Item Discount on L Items 25.00/25.00% (S\$)         1,691.68

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		11.00	11.00
	Sub Total (S\$)	11.00	11.00

## Recommended Labour

No	Particulars	Lab.	.Туре	Repairer's	Amount
Lab	our Items				
1	PANEL BEATING	Ne	ew	800.00	525.00
2	SPRAYPAINT	Ne	ew	600.00	500.00
3	CHECK WIRING	Ne	ew	50.00	30.00
4	TUFF KOTE	Ne	ew	50.00	30.00
5	TOWING FEE	Ne	ew	60.00	60.00
		Gross Labour Cost	t (S\$)	1,560.00	1,145.00
		Report was unsubmitted during this print-o	out.		

< END OF ESTIMATES >