



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 468Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH	NOT NECESSARY	1,951.10	-
2	FRONT DOOR HINGE RH @ \$98.10 EACH	NOT NECESSARY	196.20	-
1	FRONT DOOR INNER TRIM RH	NOT NECESSARY	1,198.20	-
1	FRONT DOOR LOCK RH	NOT NECESSARY	342.58	-
1	FRONT DOOR WINDOW MOULDING RH	NOT NECESSARY	198.10	-
1	FRONT DOOR WEATHER STRIP INNER RH	NOT NECESSARY	302.10	-
1	FRONT DOOR WEATHER STRIP OUTER RH	NOT NECESSARY	298.90	-
1	FRONT DOOR STEP GARNISH RH	NOT NECESSARY	342.00	-
1	FRONT WHEEL HOUSING TOP GARNISH RH	NOT NECESSARY	398.10	-
1	FRONT STEP PANEL UPPER RH	NOT NECESSARY	259.10	-
1	FRONT STEP PANEL LOWER RH	NOT NECESSARY	298.70	-
1	FRONT STEP PANEL GARNISH RH	NOT NECESSARY	198.85	-
1	FRONT CENTER PILLAR RH	DENTED	1,872.00	881.70
1	REAR SLIDING DOOR RH	DENTED	2,167.00	1,611.00
1	REAR SLIDING DOOR WEATHERSTRIP RH	NOT NECESSARY	143.00	-
1	REAR SLIDING DOOR RAILING RH	NOT NECESSARY	392.00	-
1	FRONT RIM RH	NOT NECESSARY	599.10	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	723.00	-
1	FRONT WHEEL BEARING RH	NOT NECESSARY	239.80	-
1	FRONT WHEEL BEARING HUB RH	NOT NECESSARY	341.20	-
1	FRONT ABSORBER RH	NOT NECESSARY	791.80	-
1	FRONT LOWER ARM RH	NOT NECESSARY	749.80	-
	LESS 25% DISCOUNT		-3,500.66	-623.18
			10,501.97	1,869.52
<u>SPECIAL NETT ITEMS</u>				
1	FRONT DOOR INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT DOOR ROC STICKER (SN)	NOT NECESSARY	40.00	-
1	REAR SLIDING DOOR COMPANY STICKER (SN)	NECESSARY	1,000.00	500.00
			1,090.00	500.00

Report Ref No. CS/AGI22010317/Dvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS.	NOT NECESSARY	300.00	-
	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS.		2,400.00	700.00
	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS.		2,400.00	700.00
	TO TUFF COAT DAMAGED AREAS.		200.00	40.00
	TO RNR FRONT UNDERCARRIAGE SYSTEM TO FACILITATE REPAIRS.	NOT NECESSARY	400.00	-
	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS.	NOT NECESSARY	400.00	-
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS.	NOT NECESSARY	400.00	-
	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS.	NOT NECESSARY	300.00	-
			6,920.00	1,440.00
GRAND TOTAL			18,511.97	3,809.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/AGI22010317/Dvy3m4

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.