

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010321/AYA3Q2**Date:** 10/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800051437
Claimant Vehicle No :	SNB9458C	Insured Vehicle No :	SFE2128E
Date of Loss:	01/10/2022	Nature of Claim:	TP
		Claim No:	3246106368SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB9458C		
Make & Model:	OPEL GRANDLAND X, 1.2 T 6 (A)	Engine No:	10TMA30119147
Reg. Date:	23/09/2021 (Man. Year: 2021)	Chassis No:	W0VZRHNS6M6819397
Colour:	Grey	Odometer:	20291 km
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,827.60	5,315.10	13,512.50	71.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	950.00	2,640.00	73.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,417.60	6,265.10	16,152.50	72.05
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	22,417.60	5,000.00	17,417.60	77.70
+ GST 8.00/8.00% (S\$)	1,793.41	400.00	1,393.41	77.70
Nett Amount (S\$)	24,211.01	5,400.00	18,811.01	77.70
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,907.45		

INSPECTION

Date of Assignment:	12/10/2022		
Date Inspected:	12/10/2022	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Deformed	1,309.00 FL	*1,309.00 FL
2	1		*RR BUMPER LH	Not Necessary	634.00 FL	*- FL
3	1		*RR BUMPER RH	Not Necessary	634.00 FL	*- FL
4	1		*RR BUMPER LOW GARNISH (SILVER)	Not Necessary	438.00 FL	*- FL
5	1		*RR BUMPER REFLECTOR RH	Not Necessary	94.00 FL	*- FL
6	1		*RR BUMPER REFLECTOR LH	Not Necessary	94.00 FL	*- FL
7	1		*RR BUMPER SIDE RETAINER RH (INNER) - BRACKET	Not Necessary	120.00 FL	*- FL
8	1		*RR BUMPER SIDE RETAINER RH (OUTER) - GUIDE	Not Necessary	256.00 FL	*- FL
9	1		*RR BUMPER CENTER RETAINER - ENERGY ABSORBER	Cracked	158.00 FL	*158.00 FL
10	1		*RR BUPMER SIDE RETAINER LH (INNER) - BRACKET	Not Necessary	120.00 FL	*- FL
11	1		*RR BUMPER SIDE RETAINER LH (OUTER) - GUIDE	Not Necessary	256.00 FL	*- FL
12	1		*RR BUMPER REINFORCEMENT	Dented	886.00 FL	*886.00 FL
13	2		*RR BUMPER REVERSE SENSOR	Not Necessary	368.00 FL	*- FL
14	1		*RR BUMPER REVERSE SENSOR HOLDER	Necessary	139.00 FL	*139.00 FL
15	4		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	60.00 FL	*60.00 FL
16	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	268.00 FL	*- FL
17	1		*RR TAILGATE	Cracked	2,632.00 FL	*2,632.00 FL
18	1		*RR TAILGATE HANDS FREE MOTION SENSOR	Not Necessary	841.00 FL	*- FL
19	1		*RR TAILGATE HANDS FREE SWITCH	Not Necessary	145.00 FL	*- FL
20	1		*RR TAILGATE CLOSE SWITCH (INNER)	Not Necessary	165.00 FL	*- FL
21	1		*RR TAILGATE CLOSE SWITCH (OUTER)	Not Necessary	188.00 FL	*- FL
22	1		*RR TAILGATE NUMBER PLATE LAMP	Not Necessary	139.00 FL	*- FL
23	1		*RR REVERSE CAMERA ASSY	Not Necessary	842.00 FL	*- FL
24	1		*RR TAILGATE OPEL LOGO	Necessary	186.00 FL	*186.00 FL
25	1		*RR TAILGATE GRANDLAND X EMBLEM	Necessary	198.00 FL	*198.00 FL
26	1		*RR TAILGATE TURBO EMBLEM	Necessary	171.00 FL	*171.00 FL
27	1		*RR TAILGATE WEATHER STRIP	Not Necessary	218.00 FL	*- FL
28	1		*RR TAILGATE LOCK	Not Necessary	252.00 FL	*- FL
29	1		*RR TAILGATE LOCK CATCHER - STRIKER	Not Necessary	131.00 FL	*- FL
30	1		*RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	Not Necessary	378.00 FL	*- FL
31	1		*RR TAILGATE STOPED	Not Necessary	59.00 FL	*- FL
32	1		*RR TAILGATE POWER DAMPER, ACTUATOR, RH	Not Necessary	1,417.00 FL	*- FL
33	1		*RR TAILGATE POWER DAMPER, ACTUATOR, LH	Not Necessary	1,417.00 FL	*- FL
34	1		*RR TAILGATE INNER TRIM BOARD	Not Necessary	921.00 FL	*- FL
35	1		*RR TAILGATE LAMP RH	Not Necessary	457.00 FL	*- FL
36	1		*RR TAILGATE LAMP LH	Not Necessary	457.00 FL	*- FL
37	1		*RR TAILGATE GLASS WITH MLDG	Not Necessary	776.00 FL	*- FL
38	1		*RR TAILLAMP RH	Not Necessary	436.00 FL	*- FL
39	1		*RR TAILLAMP LH	Not Necessary	436.00 FL	*- FL
40	1		*RR END PANEL	Not Necessary	1,236.00 FL	*- FL
41	1		*RR END PANEL TOP GARNISH	Not Necessary	382.00 FL	*- FL
42	10		*RR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
43	10		*RR END PANEL GARNISH CLIP	Not Necessary	40.00 FS	*- FS
44	10		*RR TAILGATE INNER TRIM CLIP	Not Necessary	40.00 FS	*- FS
45	1		*RR NUMBER PLATE	Cracked	60.00 FS	*60.00 FS
46	1		*RR BODY SEAL	Not Necessary	60.00 FS	*- FS
47	1		*RR WINDSCREEN SEALANT	Necessary	65.00 FS	*40.00 FS
48	1		*RR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*20.00 FS
49	1		*RR WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,859.00	5,889.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,031.40	573.90
Total Parts (\$)	18,827.60	5,315.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,000.00	400.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	250.00
3	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	0.00
4	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	100.00	0.00
5	REMOVE AND REFIX SEAT CUSHION / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	200.00	0.00
6	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	100.00	50.00
7	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	100.00	50.00
8	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	160.00	80.00
9	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	0.00
10	TO REMOVE AND REPLACE EXHAUST PIPE	New	200.00	0.00
11	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	180.00	120.00
12	TO PERFORM DIAGNOSTIC RESET ON FAULTY CODE	New	350.00	0.00
Gross Labour Cost (S\$)			3,590.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >