

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010323/TVY3M4**Date:** 11/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00008912100
Claimant Vehicle No :	SLA9198G	Insured Vehicle No :	SLH3995A
Date of Loss:	15/10/2022	Nature of Claim: TP	Claim No: SNM22D207403/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA9198G		
Make & Model:	TOYOTA LEXUS, 2.0 RX200T EXECUTIVE 2WD (A)	Engine No:	8ARW183994
Reg. Date:	29/01/2016 (Man. Year: 2015)	Chassis No:	JTJZAMCA502001288
Colour:	Black	Odometer:	141379 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60R18	Rear Tyre Size:	235/60R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,759.20	7,171.16	9,588.04	57.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	1,680.00	2,650.00	61.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,089.20	8,851.16	12,238.04	58.03
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	21,089.20	7,100.00	13,989.20	66.33
+ GST 8.00/8.00% (S\$)	1,687.14	568.00	1,119.14	66.33
Nett Amount (S\$)	22,776.34	7,668.00	15,108.34	66.33

INSPECTION

Date of Assignment:	17/10/2022	
Date Inspected:	18/10/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2023)
Parts:	143	TOYOTA LEXUS 2.0 RX200T EXECUTIVE 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA9198G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,850.50 FL	*1,850.50 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	241.20 FL	*241.20 FL
3	1		*TAILGATE LEXUS EMBLEM	Necessary	85.60 FL	*85.60 FL
4	1		*TAILGATE CENTRE EMBLEM	Necessary	78.30 FL	*78.30 FL
5	1		*TAILGATE RX200T EMBLEM	Necessary	75.10 FL	*75.10 FL
6	1		*TAILGATE RH LAMP	Not Necessary	556.80 FL	*- FL
7	1		*TAILGATE LH LAMP	Not Necessary	556.80 FL	*- FL
8	1		*TAILGATE LOCK	Not Necessary	322.40 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	718.90 FL	*- FL
10	1		*TAILGATE REVERSE CAMERA	Not Necessary	933.20 FL	*- FL
11	1		*REAR BUMPER	Deformed	1,155.30 FL	*1,155.30 FL
12	1		*REAR BUMPER LOWER GARNISH	Deformed	314.50 FL	*314.50 FL
13	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Necessary	381.00 FL	*- FL
14	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Not Working	381.00 FL	*381.00 FL
15	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Not Working	381.00 FL	*381.00 FL
16	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Necessary	381.00 FL	*- FL
17	1		*REAR BUMPER RH EXHAUST CHROME	Not Necessary	211.90 FL	*- FL
18	1		*REAR BUMPER LH EXHAUST CHROME	Not Necessary	211.90 FL	*- FL
19	1		*REAR BUMPER RH REFLECTOR	Not Necessary	78.60 FL	*- FL
20	1		*REAR BUMPER LH REFLECTOR	Not Necessary	78.60 FL	*- FL
21	1		*REAR BUMPER INNER SPONGE	Cracked	147.80 FL	*147.80 FL
22	1		*REAR BUMPER REINFORCEMENT	Bent	730.60 FL	*730.60 FL
23	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	83.10 FL	*- FL
24	1		*REAR BUMPER LH SIDE RETAINER	Cracked	83.10 FL	*83.10 FL
25	1		*REAR BUMPER RH BRACKET	Not Necessary	88.30 FL	*- FL
26	1		*REAR BUMPER LH BRACKET	Not Necessary	88.30 FL	*- FL
27	1		*REAR BUMPER LOWER COVER	Not Necessary	234.90 FL	*- FL
28	1		*RH TAILLAMP ASSY	Cracked	910.40 FL	*910.40 FL
29	1		*RH TAILLAMP LOWER BRACKET	Cracked	90.30 FL	*90.30 FL
30	1		*RH TAILLAMP PANEL	Not Necessary	189.30 FL	*- FL
31	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	40.00 FL	*- FL
32	1		*LH TAILLAMP ASSY	Cracked	910.40 FL	*910.40 FL
33	1		*LH TAILLAMP LOWER BRACKET	Cracked	90.30 FL	*90.30 FL
34	1		*LH TAILLAMP PANEL	Not Necessary	189.30 FL	*- FL
35	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	40.00 FL	*- FL
36	1		*END PANEL	Repair	832.10 FL	*- FL
37	1		*END PANEL INNER GARNISH	Deformed	287.00 FL	*287.00 FL
38	1		*SPARE TYRE PANEL TOP COVER BOARD	Not Necessary	588.00 FL	*- FL
39	1		*REAR FENDER RH INNER TRIM BOARD	Not Necessary	618.90 FL	*- FL
40	1		*REAR FENDER LH INNER TRIM BOARD	Not Necessary	618.90 FL	*- FL
41	1		*EXHAUST SILENCER	Not Necessary	1,865.40 FL	*- FL
42	1		*EXHAUST SILENCER GASKET	Not Necessary	68.00 FL	*- FL
43	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
44	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
45	1		*TAILGATE SEALANT	Not Necessary	100.00 FS	*- FS
46	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
48	1		*SET REAR BUMPER LOWER COVER CLIPS	Necessary	60.00 FS	*20.00 FS
49	1		*SET REAR FENDER RH INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
50	1		*SET REAR FENDER LH INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
51	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
52	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,538.00	7,952.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,778.80	781.24
Total Parts (\$\$)	16,759.20	7,171.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	100.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	30.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS AND REPLACE SEALANTS	New	280.00	120.00
6	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	180.00	40.00
7	REMOVE AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	220.00	60.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	40.00
9	REMOVE AND REPLACE REAR INNER TRIMS AND GARNISH TO ASSIST REPAIR	New	350.00	60.00
10	REMOVE AND REPLACE EXHAUST SILENCERS TO ASSIST REPAIR	New	380.00	0.00
Gross Labour Cost (S\$)			4,330.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >