

ACIS REC BY: Toupin

REP:

INC.

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP'

Date: _____ Person Contacted: Junon

Vehicle: IN / OUT

Veh No: SMD 8810K Yr Regn: 2019 Aug

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz Viano C.C. 2143

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 339889 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WD F-44781323611699

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R16

R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GT Radial

Front

Rear

R/Bal. 0 mm

R/Bal. 0 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 17/10/22

Survey held at

Comfort by my

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. \$ _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. invs (\$ _____)

Others

☐ : Weekend (\$ _____)

Rep. Form: _____

Lum. Sum / L.Bal. (\$ _____)

REPAIR ESTIMATE*

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	LH SLIDING DOOR			\$2,370.20
1	TAILLAMP ASSY LH			\$622.44
SUB TOTAL				\$2,992.64
LESS 20%				\$598.52
DISCOUNTED TOTAL				\$2,394.12
REAR BUMPER MAT (METAL)				x \$50.00
COMFORTDELGRO LOGO				net \$80.00
MAXICAP LOGO				net \$80.00
Labour Charge				
PANEL BEATING				
SPRAY PAINT				
REMOVE / REFIX DOOR PARTS				
<p>Tanpin 9749549 up 17/10/22 @ 4pm L/S Repair after repair Tanpin & Mahanta work 2 days</p>				
TOTAL LABOUR				\$1,250.00
ESTIMATE TOTAL				\$3,854.12
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

OMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road Singapore 508619

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Date/Time: 17.10.2022 15:52

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO305533474

OMER

S CITYCAB PTE LTD

OMER NO 7010070

ESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65551188

(O)

(P)

JUNT CARD NO.

REGN NO:

SHD8810K

MILEAGE

MAKE:

MERCEDES BENZ

FUEL

E.....1/2.....F

MODEL

OTHERS - C

17.10.2022

DATE/TIME IN

10.2022 13:30

YR OF MANU

05.08.2019

TARGET DATE

CHASSIS CODE

WDF44781323611699

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 14.10.2022


ATURE: 3P.14.10.22

NO

LABOR CODE

DESCRIPTION

FRONT



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

o.: SHD8810K

JU INCOME

Vehicle No.:

SHD8810K

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard