

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7771L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR RH	BENT	3,645.00	3,645.00
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER UPPER BODY	CUT	1,342.50	1,342.50
1	REAR BUMPER LOWER BODY	NOT NECESSARY	352.50	-
1	ALUMINUM ALLOY WHEEL RH	CUT	682.00	682.00
1	REAR DOOR WINDOW REGULATOR ASSY RH	NOT NECESSARY	265.00	-
1	OUT SKIRT PANEL RIGHT SIDE WALL	TO REPAIR SEE LABOUR	395.00	-
	LESS 20% DISCOUNT		-1,336.40	-1,133.90
			5,345.60	4,535.60
	NETT ITEMS			
1	RR DR (R) 100% ELECTRIC LOGO CTPL (N)	NECESSARY	72.00	72.00
1	REAR BUMPER RIGHT SIDE LINE STICKER (N)	CUT	12.00	12.00
1	REAR DOOR (RIGHT SIDE) LINE STICKER (N)	CUT	12.00	12.00
	LESS 10% DISCOUNT		-	-9.60
			96.00	86.40
	SPECIAL NETT ITEMS			
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER RH AND OUT SKIRT PANEL RIGHT SIDE WALL.		1,100.00	600.00
	SPRAY PAINTING CHARGE.		1,200.00	850.00
	TUFF KOTE.		80.00	30.00
	TRANSFER OF DOOR .		120.00	60.00
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
			2,580.00	1,570.00
	GRAND TOTAL		8,071.60	6,242.00

Report Ref No. NS/INC22010327/Tncq2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		6,242.00
(CONFIRMED)		

Report Ref No. NS/INC22010327/Tncq2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser