

ASS. REC:BY: Taufikh

REP:

INC. NS/INC22010327/Tnc

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated cost: \_\_\_\_\_

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. MT/1192863-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Ms Lone

Veh No: SHA 7771L Yr Regn: 2022, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BYD New E6 C.C. 70 KW

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 15126 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: L10CE4DC9N 0065131

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: W / S/Rim / STD A/Rim or

Tyre Size: F: 215/55 R17

R: 215/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Chao Yang

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 17/6/22

Survey held at

Confut Longy

Des. of Damages: F/R / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh confirmed final fig: \$6242 / 3 days

(red, 1779.6, 22%)

Date/Time, File Pass to?

1) 16/11/22

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. invs (\$

☐ : Workshop (\$

Repair Form No: 6242

Lower Sum: 1181.7