

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010330/GQY3E2**Date:** 27/02/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00098102201
Claimant Vehicle No :	SBS3901G	Insured Vehicle No :	SLM9176G
Date of Loss:	12/10/2022	Nature of Claim: TP	Claim No: SNM22D207444/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS3901G	Engine No:	D9193479
Make & Model:	VOLVO B9TL, 9.4 D (A)	Chassis No:	YV3S4P924FA169808
Reg. Date:	19/01/2015 (Man. Year: 2014)	Odometer:	580075 km
Colour:	Multi-colour		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,124.00	1,124.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,688.00	1,688.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,812.00	2,812.00	0.00	0.00
+ GST 8.00/8.00% (S\$)	224.96	224.96	0.00	0.00
Nett Amount (S\$)	3,036.96	3,036.96	0.00	0.00

INSPECTION

Date of Assignment:	18/10/2022		
Date Inspected:	19/10/2022	Inspected At:	Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4 Singapore 489946
Estimated Period of Repair:	1.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Feb 2023)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3901G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STKR.PLS FOLD STROLLER IF CROWDED	Necessary	1.00 F	*1.00 F
2	1		*SIDE SHEETMETAL PANEL	Bent	214.00 F	*214.00 F
3	1		*EMBLEM;DECALS	Necessary	49.00 F	*49.00 F
4	1		*M8X16 ALLEN HEAD BOLT PATCHED (6PCS)	Necessary	49.00 F	*49.00 F
5	1		*SIDE SHEETMETAL PANEL	Bent	803.00 F	*803.00 F
6	1		*STKR 60KM/H (NPA)	Not Necessary	0.00 F	*- F
7	1		*STKR EMERG CTL GREEN.HORIZONTAL (NPA)	Not Necessary	0.00 F	*- F
8	1		*STKR EMERG DOOR BUTTON ORANGE (NPA)	Not Necessary	0.00 F	*- F
9	1		*STKR SBS TRANSIT OS/NS.SG BUS	Necessary	8.00 F	*8.00 F
F=Franchise part.						
Total Parts (S\$)					1,124.00	1,124.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	(2) WORKSHOP LABOUR	New	188.00	188.00
2	CONTRACTORS REPAIR CHARGES	New	1,200.00	1,200.00
3	REPAIR COST OF ADVERTISEMENT / LIVERY	New	300.00	300.00
Gross Labour Cost (\$)			1,688.00	1,688.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >