

ASIS REC BY: Tou Jia

REF:

Ce4/ASM 220/0333/Tp93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$65K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM 4822H Yr Regn: 2017 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Niro Hybrid C.C. 1580.

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 503917 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNV CC81CV 115055527

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SR / STD A/Rim or

Tyre Size: F: 205/60R16

R: a -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 18/10/22

Survey held at ucl solution.

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____
Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. invs (\$ _____)

☐ : Weekend (\$ _____)

☐ : S + RS. \$ _____

Photos _____

Others _____

Report Formed: _____

Lum Sum / L.Bal. (\$ _____)

TOTAL

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 AAS Kaki Bukit Centre #04-01 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 17/10/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SLM4822H		
MODEL	: KIA NIRO HYBRID 1.6		
CHASSIS NO			
ACCIDENT DETAILS	DATE : 14-Oct-22		
	TIME : 19:30HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE	1	\$ 1,355.80	\$ 1,355.80
2	TAILGATE LOGO	1	\$ 92.00	\$ 92.00
3	TAILGATE EMBLEM 'NIRO'	1	\$ 62.00	\$ 62.00
4	TAILGATE EMBLEM 'HYBRID'	1	\$ 62.00	\$ 62.00
5	TAILGATE EMBLEM 'C&C'	1	\$ 89.00	\$ 89.00
6	TAILAGTE INNER BOARD	1	\$ 680.90	\$ 680.90
7	TAILAGTE LOCK	1	\$ 322.50	\$ 322.50
8	TAILGATE WEATHERSTRIP	1	\$ 260.00	\$ 260.00
9	TAILGATE WINDSCREEN MOULDING	1	\$ 180.00	\$ 180.00
10	REAR BUMPER	1	\$ 720.00	\$ 720.00
11	REAR BUMPER LOWER	1	\$ 410.00	\$ 410.00
12	REAR BUMPER UNDER COVER	1	\$ 320.50	\$ 320.50
13	REAR BUMPER SKID PLATE	1	\$ 190.50	\$ 190.50
14	REAR BUMPER SIDE RETAINER	2	\$ 89.60	\$ 179.20
15	REAR BUMPER TOWING COVER	1	\$ 80.00	\$ 80.00
16	REAR BUMPER REFLECTOR	2	\$ 198.20	\$ 396.40
17	REAR BUMPER REINFORCEMENT	1	\$ 480.00	\$ 480.00
18	REAR BUMPER REINFORCEMENT BRACKET	2	\$ 122.30	\$ 244.60

19	REAR BUMPER REINFORCEMENT HOLDER	25	\$ 30.00	\$ 150.00
20	REAR BUMPER SENSOR	4	\$ 211.00	\$ 844.00
21	REAR BUMPER SENSOR RUBBER	4	\$ 60.50	\$ 242.00
22	REAR BUMPER SENSOR WIREHARNESS	1	\$ 388.90	\$ 388.90
23	REAR END PANEL	1	\$ 758.90	\$ 758.90
24	REAR END PANEL TOP GARNISH	1	\$ 260.50	\$ 260.50

TOTAL PRICE \$ 8,769.70

LESS 10% \$ 876.97

SUB TOTAL PRICE \$ 7,892.73

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	TAILGATE INNER BOARD CLIPS(SET)	1	\$ 20.00	\$ 20.00
3	TAILGATE WINDSCREEN SEALANT	1	\$ 120.00	\$ 120.00
4	REAR BUMPER CLIPS(SET)	1	\$ 20.00	\$ 20.00
5	REAR END PANEL INSULATOR SEAL	1	\$ 150.00	\$ 150.00
6	REAR END PANEL TOP GARNISH CLIPS(SET)	1	\$ 20.00	\$ 20.00

TOTAL \$ 380.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 1,600.00		800
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,200.00		700
3	TUFF COAT	\$ 250.00		30
4	WIRING CHECK	\$ 120.00		30
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00		30
6	TRANSFER TAILGATE MECHANISM	\$ 120.00		x
7	TRANSFER TAILGATE WINDSCREEN	\$ 120.00		x

TOTAL

\$3,510.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,272.73

TOTAL LABOUR COST : \$ 3,510.00

Taufik 97495749 / 62563561
 wp, 18/10/22 @ 220pm
 taufik@lhamto.com
 5 days
 Resumy after repair

TOTAL REPAIR COST : \$ 11,782.73

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :