

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122010341/TVY3Q2**Date:** 16/05/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMM6588J **Insured Vehicle No :** XE333D

Date of Loss: 17/10/2022 Nature of Claim: TP Claim No: CDMCG22002197

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM6588J**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: A25A1091928

Reg. Date: 13/10/2022 (Man. Year: 2022) Chassis No: JTEAD3BH80J001271

Colour: White Odometer: 68019 km

Engine Capacity: 2487 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,512.92	5,783.32	9,729.60	62.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,610.00	2,390.00	4,220.00	63.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,122.92	8,173.32	13,949.60	63.05
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	22,122.92	6,500.00	15,622.92	70.62

INSPECTION

Date of Assignment: 18/10/2022

Date Inspected: 18/10/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 May 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM6588J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Bent	1,550.60 FL	*1,550.60 FL
2	1		*REAR DOOR INNER TRIM RH	Cracked	1,016.80 FL	*945.00 FL
3	1		*REAR DOOR SPEAKER RH	Not Necessary	225.30 FL	*- FL
4	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	183.70 FL	*- FL
5	1		*REAR DOOR OUTER HANDLE RH	Repair	364.70 FL	*- FL
6	1		*REAR DOOR OUTER STRIP MOULDING RH	Cut	158.70 FL	*158.70 FL
7	1		*REAR DOOR INNER LOCK RH	Bent	600.20 FL	*378.00 FL
8	1		*REAR DOOR INNER LOCK CATCHER RH	Not Necessary	98.60 FL	*- FL
9	1		*REAR DOOR WEATHERSTRIP RH	Torn	275.60 FL	*275.60 FL
10	1		*REAR FENDER RH	Bent	1,531.80 FL	*1,531.80 FL
11	1		*REAR FENDER INNER PANEL RH	Repair	867.10 FL	*- FL
12	1		*REAR FENDER QUARTER GLASS RH	Not Necessary	282.60 FL	*- FL
13	1		*REAR FENDER INNER COWLING RH	Missing	247.30 FL	*247.30 FL
14	1		*REAR ABS SENSOR RH	Not Necessary	417.60 FL	*- FL
15	1		*REAR SHOCK ABSORBER RH	Not Necessary	152.10 FL	*- FL
16	1		*REAR WHEEL HUP WITH BEARING RH	Not Necessary	1,008.20 FL	*- FL
17	1		*REAR ANTI ROLL BAR LINKAGE RH	Not Necessary	179.30 FL	*- FL
18	1		*REAR LOWER ARM RH	Not Necessary	524.60 FL	*- FL
19	1		*REAR KNUCKLE ARM RH	Not Necessary	465.20 FL	*- FL
20	1		*REAR ADJUSTABLE ARM RH	Not Necessary	291.60 FL	*- FL
21	1		*REAR CONTROL ARM RH	Not Necessary	271.20 FL	*- FL
22	1		*REAR WHEEL RIM RH	Not Necessary	2,604.90 FL	*- FL
23	1		*TAIL LAMP RH	Not Necessary	689.60 FL	*- FL
24	1		*REAR BUMPER	Missing	904.80 FL	*904.80 FL
25	1		*REAR BUMPER INNER SIDE GARNISH RH	Missing	204.90 FL	*204.90 FL
26	1		*REAR BUMPER LOWER	Missing	466.10 FL	*466.10 FL
27	2		*REAR BUMPER REFLECTOR	Not Necessary	171.20 FL	*- FL
28	1		*REAR BUMPER SIDE RETAINER	N/S Not Necessary /O/S Cracked	165.40 FL	*82.70 FL
29	1		*REAR BUMPER SPONGE	Not Necessary	89.30 FL	*- FL
30	4		*REAR BUMPER REVERSE SENSOR	Not Working (2 PCS ONLY)	1,591.20 FL	*570.00 FL
31	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	115.60 FL	*115.60 FL
32	1		*REAR BUMPER REVERSE SENSOR WIREHARNES	Not Necessary	288.10 FL	*- FL
33	1		*REAR DOOR SEALANT RH	Necessary	150.00 FS	*40.00 FS
34	1		*SET REAR DOOR INNER TRIM CLIP RH	Necessary	80.00 FS	*20.00 FS
35	1		*SET REAR DOOR WINDOW SIDE GARNISH CLIP	Not Necessary	60.00 FS	*- FS
36	1		*SET REAR SEAT SIDE GARNISH CLIP RH	Not Necessary	80.00 FS	*- FS
37	1		*SET SIDE SKIRT CLIP	Not Necessary	80.00 FS	*- FS
38	1		*REAR FENDER SEALANT RH	Necessary	150.00 FS	*60.00 FS
39	1		*SET REAR FENDER INNER COWLING CLIP	Necessary	60.00 FS	*20.00 FS
40	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
41	1		*REAR FENDER GLASS SEALANT RH	Necessary	80.00 FS	*40.00 FS
42	1		*REAR FENDER GLASS INNER SHIELD RH	Not Necessary	60.00 FS	*- FS
43	1		*REAR FENDER GLASS SOLAR FILM RH	Not Necessary	150.00 FS	*- FS
44	1		*SET TAIL LAMP CLIP	Not Necessary	60.00 FS	*- FS

Report was unsubmitted during this print-out.

5/16/23, 12:05 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SET REAR BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
46	1		*REAR WHEEL TYRE RH	Not Necessary	650.00 FS	*- FS
47	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
48	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	20,013.90 7,641.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	4,500.98 1,857.78
					Total Parts (\$\$)	15,512.92 5,783.32
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT REMOVE AND REPLACE PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	900.00
3	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
4	TUFF COAT	New	250.00	50.00
5	WIRING CHECK	New	250.00	40.00
6	REMOVE AND REFIX REAR FENDER GLASS LH	New	100.00	0.00
7	REMOVE AND REFIX SAFETY BELT	New	250.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	80.00
9	REMOVE & REFIX AUDIO SPEAKER	New	120.00	0.00
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	40.00
11	TRANFER REAR DOOR MECHANISM LH	New	80.00	60.00
12	REMOVE & REINSTALL REAR WINDOW GLASS RH	New	60.00	40.00
13	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	150.00
14	RESET ABS LIGHT	New	350.00	0.00
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	150.00
Gross Labour Cost (\$\$)			6,610.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >