

Vehicle Damage Assessment Report for [SMM6588J]

Estimate Created: 10/05/2023 15:31 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 10/05/2023 15:53 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Harrier
Engine Type			
License Plate Number	SMM6588J	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$6,500.00 WITH 7 WORKING DAYS	Insurlogic 4 (10/05/2023 15:53)
---	---------------------------------

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
RH rear door		1	1550.60	-25.00 %	1,162.95
RH rear door inner trim		1	945.00	-25.00 %	708.75
RH rear door outer strip moulding		1	158.70	-25.00 %	119.03
RH rear door inner lock		1	378.00	-25.00 %	283.50
RH rear door weatherstrip		1	275.60	-25.00 %	206.70
RH rear fender		1	1531.80	-25.00 %	1,148.85
RH rear fender inner cowling		1	247.30	-25.00 %	185.48
Rear bumper		1	904.80	-25.00 %	678.60
Rear bumper inner side garnish RH		1	204.90	-25.00 %	153.68
Rear bumper lower		1	466.10	-25.00 %	349.58
RH rear bumper side retainer		1	82.70	-25.00 %	62.03
Rear bumper reverse sensor		1	570.00	-25.00 %	427.50
Rear bumper reverse sensor holder		1	115.60	-25.00 %	86.70

Parts Subtotal 5,573.35

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
RH rear door sealant		1.0	40.00	0.00 %	40.00
RH rear door inner trim clips (set)		1.0	20.00	0.00 %	20.00
RH rear fender sealant		1.0	60.00	0.00 %	60.00
RH rear fender inner cowling clips (set)		1.0	20.00	0.00 %	20.00
RH rear fender glass sealant		1.0	40.00	0.00 %	40.00
Rear bumper clips (set)		1.0	30.00	0.00 %	30.00

Materials Subtotal 210.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	800.00	0.00 %	800.00
Remove and refix cushion seat/upholstery & roof lining to facilitate repair	RnR	80.00	0.00 %	80.00

Tuff coat	RnR	50.00	0.00 %	50.00
Wiring checking	RnR	40.00	0.00 %	40.00
Wheel alignment	RnR	80.00	0.00 %	80.00
Remove and refix reverse sensor and distance setting.	RnR	40.00	0.00 %	40.00
Transfer rear door mechanism	RnR	60.00	0.00 %	60.00
Remove & reinstall rear window glass RH	RnR	40.00	0.00 %	40.00
Remove and refix rear undercarriage	RnR	150.00	0.00 %	150.00
To check diagnostics o vehicle management/control units, reset memories to specification etx.	RnR	150.00	0.00 %	150.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
RH rear door outer handle	Medium	0.00	0.00 %	0.00
RH rear fender inner panel	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	900.00	0.00 %	900.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,490.00

Paint Labor Subtotal 900.00

Labor Subtotal 2,390.00

Summary

Repair Cost	8,173.35
Discount(20 %)	(1,634.66)
	6,538.69
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	6,538.69