

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010343/EVY3Q2**Date:** 08/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00095042201

Claimant Vehicle No : FBU1629X **Insured Vehicle No :** SJE3381K

Date of Loss: 14/10/2022 Nature of Claim: TP Claim No: SNM22D207421/C03/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBU1629X**

Make & Model: YAMAHA NMAX155, 155cc ABS CVT Engine No: G3L8E1202757

Reg. Date: 23/08/2022 (Man. Year: 2022) Chassis No: MH3SG5680NK143683

Colour: Blue Odometer: 9444 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 60/70-13 Rear Tyre Size: 70/80-13

Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	503.10	503.10	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	150.00	100.00	50.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	653.10	603.10	50.00	7.66
+ GST 7.00/7.00% (S\$)	45.72	42.22	3.50	7.66
Nett Amount (S\$)	698.82	645.32	53.50	7.66

INSPECTION

Date of Assignment: 18/10/2022

Date Inspected: 19/10/2022 Inspected At: Southern Motor (HQ)
BLK 1006 BUKIT MERAH LANE 2, #01-10
Singapore 159762

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Nov 2022)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS CVT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBU1629X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT FOOT PLATE	Cut	240.00 FN	*240.00 FN
2	1		*BRAKE LEVER LH	Cut	22.00 FN	*22.00 FN
3	1		*BRAKE LEVER RH	Cut	22.00 FN	*22.00 FN
4	1		*HANDLE BAR	Bent	75.00 FN	*75.00 FN
5	1		*EXHAUST PIPE COVER	Cut	60.00 FN	*60.00 FN
6	1		*REAR GIVI BOX	Cut	140.00 FN	*140.00 FN
					Sub Total (S\$)	559.00
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	55.90
					Total Parts (S\$)	503.10

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	150.00	100.00
Gross Labour Cost (\$\$)			150.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >