



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBJ 21M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER CLIP X10	NECESSARY	12.00	12.00
1	PANEL ASSY-FENDER,RH	DENTED	1,187.90	1,187.90
1	BRACKET-FENDER MTG,LH	NOT NECESSARY	32.50	-
1	INSULATOR-FENDER LH	NOT NECESSARY	78.70	-
1	COVER-FR BUMPER UPR	BROKEN	615.60	615.60
1	LAMP ASSY-DAY RUNNING LIGHT,LH	NOT NECESSARY	852.50	-
1	LAMP ASSY-HEAD,LH	CUT	3,185.00	3,185.00
1	GUARD ASSY-FRONT WHEEL,LH	NOT NECESSARY	80.90	-
1	GARNISH ASSY-FNDR SIDE,LH	CUT	107.20	107.20
1	COVER-FR BUMPER,LWR	CUT	408.10	408.10
1	LAMP ASSY-FRONT FOG,LH	NOT NECESSARY	525.60	-
1	AIR DUCT-FR BUMPER,LH	NOT NECESSARY	31.20	-
1	MOULDING-FRONT BUMPER,LH	BROKEN	32.60	32.60
1	REINF ASSY-FR BUMPER,LH	NOT NECESSARY	18.10	-
1	BRACKET ASSY-FR BUMPER SIDE,LH (ADDITIONAL)	BROKEN	13.90	13.90
	LESS 20% DISCOUNT		-1,436.36	-1,112.46
			5,745.44	4,449.84
	<b><u>LABOUR</u></b>			
	TO CARRY OUT ACCIDENT BODY REPAIR.		1,520.00	760.00
	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREAS.		1,020.00	680.00
	TO REFOCUS LH FRONT HEADLAMPS (S.NETT).		40.00	40.00
			2,580.00	1,480.00
	<b>GRAND TOTAL</b>		<b>8,325.44</b>	<b>5,929.84</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>5,929.84</b>

Report Ref No. CS/FCI22010344/Eny3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.