

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22010358/KPA3Q2**Date:** 13/06/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001893120
Claimant Vehicle No :	SLZ8138E	Insured Vehicle No :	YP1123S
Date of Loss:	15/10/2022	Nature of Claim:	TP
		Claim No:	202222007538

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ8138E		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Elegance (A)	Engine No:	1ZR0B47415
Reg. Date:	18/05/2018 (Man. Year: 2018)	Chassis No:	MR053REH604581799
Colour:	Metallic Silver	Odometer:	49163 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,406.44	1,975.20	3,431.24	63.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,050.00	600.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,056.44	3,025.20	4,031.24	57.13
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	7,056.44	2,400.00	4,656.44	65.99
+ GST 7.00/7.00% (S\$)	493.95	168.00	325.95	65.99
Nett Amount (S\$)	7,550.39	2,568.00	4,982.39	65.99
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,170.00		

INSPECTION

Date of Assignment:	18/10/2022	
Date Inspected:	08/11/2022	Inspected At: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ8138E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	852.90 FL	*852.90 FL
2	1		*REAR BOOT EMBLEM	Necessary	51.70 FL	*51.70 FL
3	1		*REAR BOOT BADGE COROLLA	Necessary	44.40 FL	*44.40 FL
4	1		*REAR BOOT BADGE ALTIS	Necessary	49.40 FL	*49.40 FL
5	1		*REAR BOOT CENTRE MOULDING WITH CHROME	Warped / Dented	209.20 FL	*209.20 FL
6	1		*REAR BOOT INNER LOCK	Repair	432.50 FL	*- FL
7	1		*RH REAR DOOR INNER TAIL LAMP	Serviceable	509.80 FL	*- FL
8	1		*LH REAR DOOR INNER TAIL LAMP	Cracked	509.80 FL	*377.60 FL
9	1		*REAR BOOT WEATHERSTRIP	Serviceable	190.10 FL	*- FL
10	1		*RH REAR BOOT HINGE	Repair	75.60 FL	*- FL
11	1		*LH REAR BOOT HINGE	Repair	75.60 FL	*- FL
12	1		*RH OUTER TAIL LAMP	Serviceable	539.50 FL	*- FL
13	1		*LH OUTER TAIL LAMP	Dented / Cut	539.50 FL	*410.80 FL
14	1		*REAR BUMPER	Buckled	602.60 FL	*602.60 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Repair	432.50 FL	*- FL
17	1		*RH REAR BUMPER INNER BRACKET	Repair	118.70 FL	*- FL
18	1		*LH REAR BUMPER INNER BRACKET	Repair	118.70 FL	*- FL
19	1		*REAR END PANEL	Repair	727.70 FL	*- FL
20	1		*REAR END PANEL TOP TRIM	Serviceable	261.60 FL	*- FL
21	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
22	1		*SET REAR PARKING SENSORS	Serviceable	260.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,681.80	2,633.60
- List Item Discount on L Items 20.00/25.00% (S\$)	1,275.36	658.40
Total Parts (S\$)	5,406.44	1,975.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND CUT OUT BODY PANEL ,TO REWELD,RESHAPE AND REPAIR REAR END PANEL ,REAR FLOOR PANEL,REAR BODY PANEL ,TO STRAIGHTEN OUT REAR CHASSIS MEMBER ,TO REPLACE DAMAGED PARTS AND ADJUST REAR BODY AND REAR BOOT ALIGNMENT	New	700.00	400.00
2	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	650.00	600.00
3	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	50.00	20.00
4	TO PERFORM COMPUTER DIAGNOSTIC ON PARKING SYSTEM ,AND CLEAR FAULT CODES	New	150.00	0.00
5	TO APPLY ANTI-CORROSION TUFF-KOTE	New	100.00	30.00
Gross Labour Cost (\$\$)			1,650.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >