

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010361/EVCE2**Date:** 01/03/2023REFERENCE

Insured/Claimant:	LEE WAN SEONG	Policy No:	7210019320	
Date of Loss:	14/10/2022	Nature of Claim:	OD	Claim No: 1106156973SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCP2899R		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM028573
Reg. Date:	25/02/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF5XMA018779
Colour:	Black	Odometer:	20891 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$193,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	69,199.00	33,087.28	36,111.72	52.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	35,124.00	17,189.00	17,935.00	51.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	104,323.00	50,276.28	54,046.72	51.81
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	102,723.00	48,676.28	54,046.72	52.61
+ GST 8.00/8.00% (\$\$)	8,217.84	3,894.10	4,323.74	52.61
Nett Amount (\$\$)	110,940.84	52,570.38	58,370.46	52.61

INSPECTION

Date of Assignment:	19/10/2022	
Date Inspected:	18/10/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	21.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIPS	Not Necessary	79.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	293.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -RH	Not Necessary	72.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	293.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE RH	Missing	151.00 FS	*120.40 FS
8	1		*FRONT BUMPER TRIM	Not Necessary	54.00 FS	*- FS
9	1		*FRONT BUMPER BLACK TRIM -CENTRE	Not Necessary	127.00 FS	*- FS
10	1		*RADIATOR GRILLE	Not Necessary	1,881.00 FS	*- FS
11	1		*FRONT BUMPER SENSOR -OUTER	Not Necessary	266.00 FS	*- FS
12	1		*FRONT SENSOR PARK ASSIST SIDE	Cut	266.00 FS	*212.40 FS
13	4		*FRONT SENSOR SEAL RING	Necessary	10.00 FS	*8.00 FS
14	1		*WIRING SET FOR BUMPER	Not Necessary	449.00 FS	*- FS
15	1		*HORN LOW TONE -RH	Not Necessary	139.00 FS	*- FS
16	1		*SPRING SHACKLE -RH	Not Necessary	33.00 FS	*- FS
17	1		*FRONT BUMPER FOAM FILLER PC	Not Necessary	163.00 FS	*- FS
18	1		*FRONT REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
19	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	41.00 FS	*- FS
20	1		*FRONT BUMPER BRACKET -RH	Not Necessary	254.00 FS	*- FS
21	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
22	1		*STICKER FOR CAUTION	Not Necessary	16.00 FS	*- FS
23	1		*STICKER FOR AIR CONDITIONER	Not Necessary	9.00 FS	*- FS
24	1		*FRONT BRACKET FOR LOCK CARRIER	Not Necessary	154.00 FS	*- FS
25	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	64.00 FS	*- FS
26	4		*POP RIVET	Not Necessary	4.00 FS	*- FS
27	1		*FRONT FENDER -RH	Dented	1,189.00 FS	*951.20 FS
28	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
29	1		*FRONT FENDER CLOSING ELEMENT -RH	Necessary	83.00 FS	*65.84 FS
30	1		*FRONT FENDER BRACKET -RH	Bent	41.00 FS	*32.72 FS
31	6		*POP RIVET	Necessary	23.00 FS	*18.24 FS
32	1		*FRONT FENDER BRACE -FRONT RH	Bent	132.00 FS	*105.20 FS
33	1		*FRONT FENDER BRACKET FOR DEFORMATION ELEMENT	Not Necessary	55.00 FS	*- FS
34	2		*FRONT FENDER BACKET LH/RH	Not Necessary	40.00 FS	*- FS
35	1		*FRONT WHEEL HOUSING LINERS RH	Torn	299.00 FS	*238.80 FS
36	1		*FRONT WHEEL SPOILER RH	Broken	82.00 FS	*65.12 FS
37	1		*FRONT SPOILR RH	Not Necessary	40.00 FS	*- FS
38	1		*STONE CHIP GUARD BLACK -RH	Necessary	57.00 FS	*45.28 FS
39	1		*FRONT FENDER FLEDGE COVER -LONG RH	Broken	40.00 FS	*31.44 FS
40	1		*FRONT FENDER FLEDGE COVER -SHORT RH	Not Necessary	18.00 FS	*- FS
41	1		*HEADLIGHT TOP COVER-RH	Broken	49.00 FS	*38.64 FS
42	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
43	1		*BONNET IMPACT PROTECTION -CENTRE	Necessary	31.00 FS	*24.72 FS
44	2		*BONNET IMPACT PROTECTION -LH/RH	Necessary	62.00 FS	*48.48 FS
45	1		*BONNET STRICKER RH	Not Necessary	56.00 FS	*- FS
46	1		*BONNET LID LOCK	Not Necessary	228.00 FS	*- FS
47	1		*BONNET BOWDEN CABLE -CENTRE	Not Necessary	64.00 FS	*- FS
48	1		*BONNET RELEASE LEVER -CENTRE	Not Necessary	15.00 FS	*- FS
49	1		*BONNET BOWDEN CABLE -CENTRE	Not Necessary	64.00 FS	*- FS
50	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
51	1		*FRONT FENDER CHROME TRIM RH	Necessary	171.00 FS	*136.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	37.00 FS	*- FS
53	1		*FRONT FENDER CLOSING ELEMENT COVER -RH	Not Necessary	20.00 FS	*- FS
54	1		*LED HEADLIGHT WITH MATRIX BEAM -RH	Broken	8,172.00 FS	*6,537.60 FS
55	1		*HEADLIGHT HOSE	Not Necessary	42.00 FS	*- FS
56	1		*HEADLIGHT COMPENSATING HOSE 10MM	Not Necessary	45.00 FS	*- FS
57	1		*HEADLIGHT COMPENSATING HOSE -0.8MM	Not Necessary	47.00 FS	*- FS
58	1		*HEADLIGHT COMPENSATING PC	Not Necessary	45.00 FS	*- FS
59	1		*HEADLIGHT BRACKET FOR LIFT CYCLINDER -RH	Not Necessary	17.00 FS	*- FS
60	1		*HEADLIGHT LIFT CYLINDER -RH	Not Necessary	217.00 FS	*- FS
61	1		*LIFT CYLINDER HOSE -LONG	Not Necessary	107.00 FS	*- FS
62	1		*LIFT CYLINDER HOSE -SHORT	Not Necessary	53.00 FS	*- FS
63	1		*HEADLIGHT WATER RESERVOIR TANK	Not Necessary	154.00 FS	*- FS
64	1		*FRONT DOOR -RH	Repair	3,977.00 FS	*- FS
65	1		*FRONT DOOR OUTER DOOR SEAL -RH	Not Necessary	247.00 FS	*- FS
66	1		*FRONT DOOR BONDING AGENT	Not Necessary	51.00 FS	*- FS
67	1		*CLEANING SOLUTION 250 ML	Not Necessary	74.00 FS	*- FS
68	1		*CLEANING SOLUTION APPLICATOR	Not Necessary	9.00 FS	*- FS
69	1		*FRONT DOOR CATCH -RH	Not Necessary	134.00 FS	*- FS
70	1		*FRONT DOOR TRIM -RH	Necessary	171.00 FS	*136.40 FS
71	1		*EXTERIOR MIRROR MOUNTING -RH	Cut	2,015.00 FS	*1,612.00 FS
72	1		*EXTERIOR MIRROR CAP RH	Cut	308.00 FS	*246.00 FS
73	1		*EXTERIOR MIRROR GLASS -RH	Not Necessary	1,757.00 FS	*- FS
74	1		*FRONT WINDOW SLOT SEAL -RH	Not Necessary	446.00 FS	*- FS
75	1		*DATA PLATE FOR TYRE PRESSURE	Not Necessary	41.00 FS	*- FS
76	1		*REAR DOOR RH	Dented	3,977.00 FS	*3,181.60 FS
77	1		*REAR DOOR OUTER DOOR SEAL -RH	Necessary	247.00 FS	*197.20 FS
78	1		*REAR DOOR SEAL BONDING AGENT 30ML	Necessary	51.00 FS	*40.56 FS
79	1		*CLEANING SOLUTION 250 ML	Necessary	74.00 FS	*58.96 FS
80	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
81	1		*REAR DOOR ATTACHMENTS PARTS -REAR	Necessary	180.00 FS	*144.00 FS
82	1		*REAR DOOR CATCH	Not Necessary	134.00 FS	*- FS
83	1		*REAR DOOR HANDLE TRIM -RH	Missing	98.00 FS	*77.92 FS
84	1		*REAR DOOR HANDLE TRIM COVER-RH	Missing	7.00 FS	*5.36 FS
85	1		*REAR DOOR HANDLE TRIM HOUSING	Not Necessary	9.00 FS	*- FS
86	1		*REAR DOOR PEDIPHERAL LIGHT REAR -RH	Not Necessary	81.00 FS	*- FS
87	1		*REAR DOOR HANDLE SENSOR -RH	Not Necessary	255.00 FS	*- FS
88	1		*REAR DOOR HANDLE EXTERIOR -RH	Broken	47.00 FS	*37.12 FS
89	2		*UNDERLAY FRONT /REAR -RH	Necessary	8.00 FS	*6.40 FS
90	1		*REAR DOOR MOUNTING BAR -RH	Not Necessary	183.00 FS	*- FS
91	1		*SECTIONAL PART -RH	Dented	4,076.00 FS	*3,260.80 FS
92	2		*RIVETTED CAP NUT	Not Necessary	7.00 FS	*- FS
93	1		*1/4 GLASS	Necessary	780.00 FS	*638.00 FS
94	1		*1/4 GLASS PRIMER	Necessary	22.00 FS	*17.36 FS
95	1		*1/4 GLASS INSERT	Not Necessary	100.00 FS	*- FS
96	1		*REAR WHEEL HOUSING LINERS RH	Torn	299.00 FS	*238.80 FS
97	1		*REAR BUMPER	Broken	2,609.00 FS	*2,087.20 FS
98	2		*REAR BUMPER GUIDE SECTION LOWER /UPPER RH	Not Necessary	75.00 FS	*- FS
99	1		*REAR BUMPER SENSOR FOR PARK ASSIST REAR -SIDE	Not Necessary	266.00 FS	*- FS
100	4		*REAR BUMPER SENSOR SEAL	Not Necessary	10.00 FS	*- FS
101	1		*LED TAILLIGHT -RH	Not Necessary	1,269.00 FS	*- FS
102	1		*LED TAILLIGHT ATTACHMENT PARTS	Not Necessary	136.00 FS	*- FS
103	1		*LED TAILLIGHT ADHESIVE TAPES	Not Necessary	221.00 FS	*- FS
104	3		*ALUMINIUM RIM	Cut	7,677.00 FS	*6,141.60 FS
105	3		*ALUMINIUM RIM RUBBER VALVE	Necessary	12.00 FS	*8.88 FS
106	1		*FRONT WISHBONE LINK RH	Not Necessary	605.00 FS	*- FS
107	1		*LOWER ARM FRONT -RH	Not Necessary	1,057.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	2		*FRONT UPPER ARM FRONT /REAR RH	Not Necessary	1,150.00 FS	*- FS
109	1		*FRONT WHEEL HOUSING BEARING -RH	Not Necessary	1,070.00 FS	*- FS
110	1		*FRONT LOWER ARM SWIVEL JOINT	Not Necessary	214.00 FS	*- FS
111	1		*FRONT WHEEL HUB -RH	Not Necessary	499.00 FS	*- FS
112	1		*FRONT WHEEL HUB BEARING -RH	Not Necessary	273.00 FS	*- FS
113	1		*FRONT SUSPENSION FORKS -RH	Not Necessary	293.00 FS	*- FS
114	2		*FRONT COUPLING ROD	Not Necessary	258.00 FS	*- FS
115	1		*FRONT GAS SHOCK ABSORBER -RH	Not Necessary	342.00 FS	*- FS
116	1		*FRONT TIE ROD -RH	Not Necessary	109.00 FS	*- FS
117	1		*FRONT TIE ROD END RH	Not Necessary	217.00 FS	*- FS
118	1		*REAR LOWER ARM -RH	Not Necessary	963.00 FS	*- FS
119	1		*REAR WISHBONE UPPER-RH	Not Necessary	624.00 FS	*- FS
120	1		*REAR WISHBONE UPPER-RH FRONT	Not Necessary	137.00 FS	*- FS
121	1		*REAR WISHBONE -RH REAR	Not Necessary	501.00 FS	*- FS
122	1		*REAR TRACK ROD REAR -RH REAR	Not Necessary	188.00 FS	*- FS
123	1		*REAR WHEEL BEARING HOUSING RH	Not Necessary	1,097.00 FS	*- FS
124	1		*REAR WHEEL HUB BEARING -RH	Not Necessary	723.00 FS	*- FS
125	1		*REAR GAS SHOCK ABSORBER -RH	Not Necessary	342.00 FS	*- FS
126	1		*REAR COUPLING ROD -RH	Not Necessary	94.00 FS	*- FS
127	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
128	1		*ACYRLIC SEALER	Necessary	180.00 FS	*180.00 FS
129	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
130	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
131	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
132	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
133	1		*RHS FRONT TYRE	Torn	430.00 FS	*430.00 FS
134	1		*RHS REAR TYRE (NPA)	Not Necessary	0.00 FS	*- FS
135	1		*SUNDRIES	Necessary	1,000.00 FS	*173.44 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					69,199.00	33,087.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	800.00	680.00
4	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER ,BONNET ,RHS FRONT DOOR ,RHS REAR DOOR AND RHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	4,800.00	2,250.00
5	TO RESRPAY FRONT BUMPER ,RHS FRONT FENDER ,BONNET ,RHS FRONT DOOR ,RHS WING MIRROR AND RHS REAR DOOR	New	5,500.00	2,900.00
6	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
7	TO RENEW RHS 1/4 GLASS TO FACILITATE RENEWAL OF RHS REAR FENDER	New	300.00	300.00
8	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	400.00
9	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
11	TO REMOVE AND REINSTALL REAR SEAT ,BACK REST HAT TRAY ,CD PILLAR TRIMS ,LUGGAGE COMPARTMENT TRIMS DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
12	TO DISMANTLE AND RENEW REAR BUMPER ,TO REMOVE AND REINSTALL RHS SILL PANEL TRIM ,TO CUT OUT AND WELD RHS REAR FENDER ,REORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	6,400.00	3,000.00
13	TO RESPRAY REAR BUMPER ,RHS REAR FENDER ,RHS SILL PANEL TRIM ,ROOF CHANNEL ,RHS SILL PANEL ,DRAIN CHANNEL ,DOOR ENTRANCES AND REAR END PANELLING	New	6,500.00	2,475.00
14	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY	New	2,400.00	0.00
15	TO REMOVE AND RENEW RHS REAR WHEEL SUSPENSION ASSY	New	2,400.00	0.00
16	TO RENEW RHS FRONT RIM WITH TYRE RHS REAR RIM WITH TYRE AND LHS FRONT RIM TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	600.00	360.00
17	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			35,124.00	17,189.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >