

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010363/EWCE2**Date:** 03/01/2023**REFERENCE**

Insured/Claimant:	LIM CHYE KWANG, EDMOND	Policy No:	2070125628	
Date of Loss:	14/10/2022	Nature of Claim:	OD	Claim No: 4783441229SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU7703U		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	DEM025004
Reg. Date:	27/08/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF41LN016210
Colour:	Red	Odometer:	41495 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$156,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,788.00	16,938.48	13,849.52	44.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,582.00	7,802.00	3,780.00	32.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,370.00	24,740.48	17,629.52	41.61
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	41,820.00	24,190.48	17,629.52	42.16
+ GST 7.00/7.00% (S\$)	2,927.40	1,693.33	1,234.07	42.16
Nett Amount (S\$)	44,747.40	25,883.81	18,863.59	42.16

INSPECTION

Date of Assignment:	19/10/2022	
Date Inspected:	18/10/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	14.0 days	

Adjuster: CHEN TSUE YEE**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT CENTRE - LOWER	Deformed	293.00 FS	*234.00 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	51.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT CENTRE - UPPER	Not Necessary	293.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE BLACK - LH	Broken	151.00 FS	*120.40 FS
9	1		*FRONT BUMPER TRIM - LH	Not Necessary	54.00 FS	*- FS
10	1		*RADIATOR GRILLE	Broken	1,754.00 FS	*1,403.20 FS
11	1		*FRONT BUMPER FOAM FILLER	Broken	212.00 FS	*169.20 FS
12	1		*FRONT BUMPER CARRIER	Dented	899.00 FS	*719.20 FS
13	1		*FRONT BUMPER BRACKET - LH	Not Necessary	254.00 FS	*- FS
14	1		*FRONT BUMPER GUIDE SECTION - LH	Broken	41.00 FS	*32.24 FS
15	1		*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
16	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
17	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
18	1		*FRONT BUMPER BRACKET	Broken	154.00 FS	*122.80 FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
20	1		*SIGNAL HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
21	1		*SPRING SHACKLE - LH	Not Necessary	33.00 FS	*- FS
22	1		*FRONT BUMPER SENSOR FRONT - INNER	Not Necessary	266.00 FS	*- FS
23	1		*FRONT BUMPER SENSOR FRONT - OUTER	Not Necessary	266.00 FS	*- FS
24	4		*FRONT SENSOR SEAL RING	Necessary	10.00 FS	*8.00 FS
25	1		*FRONT FENDER - LH	Dented	1,227.00 FS	*981.60 FS
26	1		*FRONT FENDER ATTACHMENTS PARTS	Not Necessary	225.00 FS	*- FS
27	1		*FRONT FENDER CLOSING ELEMENTS LH	Bent	81.00 FS	*64.24 FS
28	1		*FRONT FENDER BRACKET - LH	Bent	41.00 FS	*32.72 FS
29	1		*FRONT FENDER BRACE FRONT - LH	Not Necessary	132.00 FS	*- FS
30	1		*FRONT FENDER BRACKET DEFORMATION ELEMENT - LH	Not Necessary	55.00 FS	*- FS
31	2		*FRONT FENDER BRACKET - LOWER LH / RH	Not Necessary	36.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	256.00 FS	*- FS
33	1		*FRONT WHEEL SPOILER UPPER - LH	Not Necessary	82.00 FS	*- FS
34	1		*FRONT WHEEL SPOILER LOWER - LH	Not Necessary	39.00 FS	*- FS
35	1		*FRONT BUMPER TOP COVER - LH	Broken	35.00 FS	*27.52 FS
36	1		*FRONT HEADLAMP COVER - LH	Broken	49.00 FS	*38.64 FS
37	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
38	1		*BONNET ATTACHMENTS PARTS	Not Necessary	431.00 FS	*- FS
39	2		*BONNET LID HINGE LH / RH	Not Necessary	680.00 FS	*- FS
40	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	31.00 FS	*24.72 FS
41	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	62.00 FS	*48.48 FS
42	1		*BONNET STRICKER - LH	Bent	56.00 FS	*44.56 FS
43	1		*BONNET LID LOCK	Bent	228.00 FS	*182.00 FS
44	1		*FRONT BOWDEN CABLE CENTRE	Not Necessary	64.00 FS	*- FS
45	1		*FRONT BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
46	1		*FRONT BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
47	1		*FRONT BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
48	1		*FRONT LED HEADLIGHT - LH	Broken	8,172.00 FS	*6,537.60 FS
49	1		*FRONT LED HEADLIGHT HOSE	Not Necessary	42.00 FS	*- FS
50	1		*FRONT LED HEADLIGHT COMPENSATING PC 10MM	Not Necessary	45.00 FS	*- FS
51	2		*FRONT LED HEADLIGHT COMPENSATING PC 0.8MM	Not Necessary	92.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT LIFT CYLINDER LH	Not Necessary	231.00 FS	*- FS
53	1		*FRONT LIFT CYLINDER BRACKET	Distorted	7.00 FS	*5.44 FS
54	1		*FRONT LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
55	1		*WIRING SET FOR BUMPER	Not Necessary	642.00 FS	*- FS
56	1		*FRONT LOCK CARRIER	Broken	1,478.00 FS	*901.60 FS
57	1		*FRONT LOCK CARRIER BRACKET	Cracked	21.00 FS	*16.32 FS
58	1		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
59	1		*PRESSURE PIPE - LH	Not Necessary	496.00 FS	*- FS
60	1		*AIR CONDENSER	Not Necessary	683.00 FS	*- FS
61	1		*REFRIGERANT LINE SHORT	Not Necessary	186.00 FS	*- FS
62	1		*REFRIGERANT LINE LONG	Not Necessary	381.00 FS	*- FS
63	1		*REFRIGERANT LINE LOWER	Not Necessary	277.00 FS	*- FS
64	1		*REFRIGERANT PIPE	Not Necessary	585.00 FS	*- FS
65	1		*REFRIGERANT PIPE BRACKET	Not Necessary	9.00 FS	*- FS
66	6		*COOLANT 1L	Necessary	297.00 FS	*237.12 FS
67	1		*FRONT AIR GUIDE OUTER - LH	Not Necessary	51.00 FS	*- FS
68	1		*FRONT AIR GUIDE INNER - LH	Crushed	19.00 FS	*14.64 FS
69	1		*FRONT AIR GUIDE UPPER	Not Necessary	19.00 FS	*- FS
70	1		*FRONT WINDOW SLOT SEAL - LH	Not Necessary	344.00 FS	*- FS
71	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
72	1		*SUNDRIES	Necessary	400.00 FS	*86.56 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	30,788.00	16,938.48
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
4	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE	New	280.00	0.00
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED	New	4,900.00	3,000.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR	New	3,700.00	2,200.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			11,582.00	7,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >