

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010364/EVCE2**Date:** 16/12/2022REFERENCE

Insured/Claimant:	HAH YEE	Policy No:	1700012850	
Date of Loss:	13/10/2022	Nature of Claim:	OD	Claim No: 3896013997SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD7818Z		
Make & Model:	AUDI A5 CABRIOLET, 2.0 TFSI QUATTRO (A)	Engine No:	CNC048413
Reg. Date:	31/05/2016 (Man. Year: 2014)	Chassis No:	WAUZZZ8FXEN012562
Colour:	Black	Odometer:	56496 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,685.00	9,143.60	27,541.40	75.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,744.00	4,474.00	12,270.00	73.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	53,429.00	13,617.60	39,811.40	74.51
- Excess (\$\$)	4,400.00	4,400.00	0.00	0.00
(\$\$)	49,029.00	9,217.60	39,811.40	81.20
+ GST 7.00/7.00% (\$\$)	3,432.03	645.23	2,786.80	81.20
Nett Amount (\$\$)	52,461.03	9,862.83	42,598.20	81.20

INSPECTION

Date of Assignment:	19/10/2022	
Date Inspected:	18/10/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,896.00 FS	*2,316.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	271.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT LOWER - CENTER	Damaged	254.00 FS	*138.48 FS
4	3		*FRONT BUMPER PULL STRAP LOWER	Not Necessary	174.00 FS	*- FS
5	1		*FRONT BUMPER ENGINE UNDERSHIELD	Not Necessary	134.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	254.00 FS	*- FS
7	1		*RADIATOR GRILLE	Broken	966.00 FS	*772.80 FS
8	1		*QUATTRO EMBLEM	Necessary	111.00 FS	*88.80 FS
9	2		*QUATTRO EMBLEM CLIP	Necessary	17.00 FS	*13.28 FS
10	1		*FRONT BUMPER WHEEL SPOILER FRONT - RH	Crushed	66.00 FS	*52.80 FS
11	1		*FRONT BUMPER FOAM FILLER	Broken	144.00 FS	*115.20 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	985.00 FS	*- FS
13	2		*FRONT BUMPER SUPPORT	Not Necessary	29.00 FS	*- FS
14	1		*FRONT BUMPER BRACKET - RH	Not Necessary	255.00 FS	*- FS
15	1		*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
16	1		*FRONT BUMPER GUIDE PC	Bent	49.00 FS	*39.04 FS
17	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
18	1		*AIRCONDITIONER STICKER	Not Necessary	34.00 FS	*- FS
19	1		*SIGNAL HORN LOW TONE - RH	Not Necessary	214.00 FS	*- FS
20	1		*SPRING SHACKLE LOW TONE - RH	Not Necessary	28.00 FS	*- FS
21	1		*FRONT FENDER - RH	Dented	1,208.00 FS	*966.40 FS
22	1		*FRONT FENDER ATTACHMENTS PARTS	Not Necessary	60.00 FS	*- FS
23	1		*FRONT FENDER BRACE LOWER - RH	Bent	163.00 FS	*130.40 FS
24	2		*FRONT FENDER BRACKET FRONT / REAR - RH	Bent	130.00 FS	*102.88 FS
25	1		*FRONT WHEEL HOUSING LINERS RH	Crushed	197.00 FS	*157.60 FS
26	1		*FRONT WHEEL HOUSING LINERS ATTACHMENT PARTS	Not Necessary	47.00 FS	*- FS
27	1		*BONNET	Repair	3,491.00 FS	*- FS
28	1		*BONNET EDGE PROTECTION - FRONT	Torn	31.00 FS	*24.72 FS
29	1		*BONNET CATCH HOOK	Not Necessary	155.00 FS	*- FS
30	1		*BONNET LID LOCK - FRONT	Not Necessary	228.00 FS	*- FS
31	1		*BONNET LOCK COVER	Not Necessary	26.00 FS	*- FS
32	1		*HEADLIGHT MOUNTING	Broken	138.00 FS	*110.40 FS
33	1		*HEADLIGHT - RH	Broken	2,496.00 FS	*1,996.80 FS
34	1		*HEADLIGHT HOSE - RH	Not Necessary	42.00 FS	*- FS
35	1		*HEADLIGHT GAS DISCHARGE LAMP	Not Necessary	454.00 FS	*- FS
36	1		*HEADLIGHT CONTROL UNIT	Not Necessary	1,279.00 FS	*- FS
37	1		*HEADLIGHT POWER MODULE FOR DAY DRIVING	Not Necessary	635.00 FS	*- FS
38	1		*HEADLIGHT LIFT CYLINDER - RH	Broken	292.00 FS	*233.60 FS
39	1		*HEADLIGHT LIFT CYLINDER HOSE SM	Not Necessary	204.00 FS	*- FS
40	1		*HEADLIGHT LIFT CYLINDER SECURING BRACKET RH	Not Necessary	32.00 FS	*- FS
41	1		*LOCK CARRIER	Not Necessary	1,167.00 FS	*- FS
42	1		*LOCK CARRIER BRACE	Not Necessary	50.00 FS	*- FS
43	1		*LOCK CARRIER SUPPORT	Not Necessary	43.00 FS	*- FS
44	1		*CHARGE AIR COOLER	Not Necessary	628.00 FS	*- FS
45	1		*PRESSURE HOSE - RH	Not Necessary	466.00 FS	*- FS
46	1		*AIR CON CONDENSER	Not Necessary	816.00 FS	*- FS
47	1		*AIR CON CONDENSER BRACKET	Not Necessary	21.00 FS	*- FS
48	1		*AIR CON CONDENSER AIR GUIDE RH	Not Necessary	74.00 FS	*- FS
49	1		*ALUMINIUM RIM	Cut	1,458.00 FS	*1,166.40 FS
50	1		*RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
51	1		*FRONT SUPPORT FRAME	Not Necessary	4,322.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FRONT WISHBONE LINK FRONT - RH	Not Necessary	605.00 FS	*- FS
53	1		*FRONT LOWER ARM GUIDE - LOWER	Not Necessary	605.00 FS	*- FS
54	1		*FRONT LOWER ARM GUIDE - UPPER	Not Necessary	605.00 FS	*- FS
55	1		*FRONT WHEEL BEARING HOUSING	Not Necessary	1,256.00 FS	*- FS
56	1		*FRONT SWIVEL JOINT	Not Necessary	214.00 FS	*- FS
57	1		*FRONT WHEEL HUB	Not Necessary	518.00 FS	*- FS
58	1		*FRONT WHEEL BEARING ASSEMBLY	Not Necessary	651.00 FS	*- FS
59	1		*FRONT SUSPENSION FORKS RH	Not Necessary	263.00 FS	*- FS
60	2		*FRONT COUPLING ROD	Not Necessary	258.00 FS	*- FS
61	1		*FRONT SHOCK ABSORBERS	Not Necessary	1,537.00 FS	*- FS
62	1		*FRONT TRACK ROD	Not Necessary	109.00 FS	*- FS
63	1		*TIE ROD END - RH	Not Necessary	195.00 FS	*- FS
64	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
65	1		*SUNDRIES	Necessary	700.00 FS	*23.84 FS
66	1		*FRONT SUSPENSION GUIDE	Not Necessary	1,120.00 FS	*- FS
67	1		*HEADLIGHT BRACKETS - RH	Broken	118.00 FS	*94.00 FS
68	1		*HEADLIGHT WASHER COVER-RH (Supplementary)	Not Necessary	64.00 FS	*- FS
69	1		*FRONT TYRE - RHS	Torn	410.00 FS	*410.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					36,685.00	9,143.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIR CON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,600.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,000.00	1,000.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDERS RHS FRONT FENDER TOP SUPPORT AND BONNET	New	4,000.00	1,650.00
6	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	280.00
7	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	0.00
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
10	TO RESPRAY RHS FRONT DOOR (Supplementary)	New	800.00	550.00
Gross Labour Cost (\$\$)			16,744.00	4,474.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >