

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122010369/EVY3Q2**Date:** 12/12/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNA2148Z**Insured Vehicle No :** PC2078H

Date of Loss: 14/10/2022

Nature of Claim: TP

Claim No: CDMFG22002209

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNA2148Z**

Make & Model: ADIVA AD1 200, 190cc 3W

Engine No: FB20UD79585

Reg. Date: 11/06/2021 (Man. Year: 2021)

Chassis No: JF1SKEKL5MG064233

Colour: White

Odometer: 22225 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,091.60	478.80	612.80	56.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	2,070.00	780.00	27.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,941.60	2,548.80	1,392.80	35.34
+ GST 7.00/7.00% (S\$)	275.91	178.42	97.49	35.33
Nett Amount (S\$)	4,217.51	2,727.22	1,490.29	35.34

INSPECTION

Date of Assignment: 18/10/2022

Date Inspected: 20/10/2022 Inspected At:

Motor Image Enterprises Pte Ltd (Leng Kee)

25 Leng Kee Road

Singapore 159097

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Dec 2022)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA2148Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER PUNCHING FEU	Broken	518.00 FN	*518.00 FN
2	1		*ENR ABSORB FOAM EU	Not Necessary	74.00 FN	*- FN
3	1		*BRKT SD F RH	Not Necessary	14.80 FN	*- FN
4	1		*BRKT SD F LH	Not Necessary	14.80 FN	*- FN
5	1		*BEAM COMPL F EU	Not Necessary	333.00 FN	*- FN
6	1		*COVER LED F RVR	Not Necessary	148.00 FN	*- FN
7	1		*NOZZLE H L WASHERLH	Not Necessary	81.40 FN	*- FN
8	1		*NOZZLE COVER ASSYLH	Broken	55.50 FN	*55.50 FN
9	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
					Sub Total (\$\$)	1,339.50
					- Nett Item Discount on N Items 20.00/20.00% (\$\$)	247.90
					Total Parts (\$\$)	1,091.60
						478.80

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT BUMPER ,BUMPER BEAM	New	1,240.00	600.00
2	RESPRAY FRONT BUMPER & BUMPER BEAM	New	1,080.00	1,040.00
3	REMOVE & REFIT FRONT HEADLAMP WASHER PIPING	New	150.00	150.00
4	TO CONDUCT WATER SEEPAGE TEST	New	100.00	0.00
5	FAULT DIAGNOSTIC (RESER)	New	280.00	280.00
Gross Labour Cost (S\$)			2,850.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >