



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 360A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (N)	NOT NECESSARY	1,800.00	-
1	REAR TIPPER DOOR (N)	TO REPAIR SEE LABOUR	2,350.00	-
1	REAR WOODEN FRAME (N)	TO REPAIR SEE LABOUR	1,100.00	-
			5,250.00	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR NUMBER PLATE (SN)	BENT	40.00	15.00
			40.00	15.00
<b><u>LABOUR</u></b>				
	LABOUR TO CUT & WELD & RENEW REAR BUMPER. INCLUSIVE OF THE REPAIR OF REAR TIPPER DOOR & REAR WOODEN FRAME.		850.00	300.00
	LABOUR TO RENEW REAR TIPPER WOODEN CROSSMEMBER.	NOT NECESSARY	750.00	-
	TO SPRAY & PAINTING ON AFFECTED AREA.		1,300.00	400.00
	TO RUST PROOFING ON AFFECTED AREA.	NOT NECESSARY	560.00	-
			3,460.00	700.00
<b>GRAND TOTAL</b>			<b>8,750.00</b>	<b>715.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>715.00</b>

Report Ref No. CS/LIP22010370/Uvy3m4

**MARKET VALUE: \$76,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,626.00=NETT VALUE: \$67,374.00**

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**