



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 7163P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOT	DENTED	1,615.30	1,615.30
1	REAR BOOT GLASS SEALANT	NECESSARY	42.00	42.00
1	REAR BOOT EMBLEM	NECESSARY	105.00	105.00
1	REAR BOOT REFLECTOR (RIGHT)	SCRATCHED	266.00	266.00
1	REAR BUMPER REVERSE SENSOR	SERVICEABLE	250.00	-
1	REAR BUMPER SUPPORT BRACKET	NOT NECESSARY	145.00	-
1	REINFORCEMENT	NOT NECESSARY	602.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,102.00	-
	LESS 5% DISCOUNT		-	-101.42
			4,127.30	1,926.88
	<b><u>LABOUR</u></b>			
	TO REMOVE & REFIX REAR GLASS.		150.00	120.00
	TRANSFER BOOT COMPONENTS.		150.00	60.00
	CHECK WIRING.		80.00	20.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	300.00
	PAINT WORK.		700.00	400.00
			1,680.00	900.00
	<b>GRAND TOTAL</b>		<b>5,807.30</b>	<b>2,826.88</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,200.00</b>

Report Ref No. CS/SMR22010371/Uwy3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.