

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22010373/GVY3Q2**Date:** 31/10/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000276
<b>Claimant Vehicle No :</b>	SH9408G	<b>Insured Vehicle No :</b>	SLH8929J
Date of Loss:	18/10/2022	Nature of Claim:	TP
		Claim No:	M2205822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH9408G</b>	Engine No:	G4LEJU192066
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU141569
Reg. Date:	02/04/2019 (Man. Year: 2018)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,658.12	1,055.16	602.96	36.36
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,330.00	840.00	490.00	36.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,999.12</b>	<b>1,906.16</b>	<b>1,092.96</b>	<b>36.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>(S\$)</b>	2,999.12	1,500.00	1,499.12	49.99
<b>+ GST 7.00/7.00% (S\$)</b>	209.94	105.00	104.94	49.99
<b>Nett Amount (S\$)</b>	<b>3,209.06</b>	<b>1,605.00</b>	<b>1,604.06</b>	<b>49.99</b>

INSPECTION

Date of Assignment:	19/10/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	19/10/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 31 Oct 2022)

**Parts:** 192      HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SH9408G)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Cracked	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER LWR CTR MOULDING	Not Necessary	155.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Not Necessary	148.10 FL	*- FL
7	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	55.80 FL	*- FL
8	1		*REAR BUMPER TOWING COVER	Cut	98.80 FL	*98.80 FL
9	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	*50.00 F
10	1		*REAR BUMPER REVERSE SENSOR	Cut	180.00 F	*180.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,015.15</b>	<b>1,261.45</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	357.03	206.29
<b>Total Parts (\$\$)</b>	<b>1,658.12</b>	<b>1,055.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
			<b>Sub Total (\$\$)</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ADVERTISEMENT STICKER	New	200.00	200.00
2	PANEL BEATING	New	750.00	350.00
3	SPRAY PAINTING CHARGE	New	300.00	250.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	40.00
			<b>Gross Labour Cost (\$\$)</b>	<b>840.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**