

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22010377/UVY3Q2**Date:** 01/11/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SFG6918E**Insured Vehicle No :** SLD418R

Date of Loss: 04/10/2022

Nature of Claim: TP

Claim No: 2022 22007269KC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFG6918E**

Make & Model: MERCEDES-BENZ E200 (R17), 2.0 (A)

Engine No: 27492030469559

Reg. Date: 15/01/2016 (Man. Year: 2015)

Chassis No: WDD2120342B242554

Colour: Grey

Odometer: 77718 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size: 265/35Z R18

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,807.88	3,050.91	756.97	19.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	830.00	450.00	35.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,087.88	3,880.91	1,206.97	23.72
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	5,087.88	3,100.00	1,987.88	39.07
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/10/2022

Date Inspected: 27/10/2022

Inspected At:

Siang Hui Motor Works (HQ)

3006 Ubi Road 1, #01-338

Singapore 408700

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2022)
Parts:	143	MERCEDES-BENZ E200 (R17) 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFG6918E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	1,910.68 FL	*1,710.68 FL
2	1		*REAR BUMPER LOWER GARNISH	Cut	253.35 FL	*253.35 FL
3	1		*REAR BUMPER MOULDING	Cracked	487.38 FL	*487.38 FL
4	1		*REVERSE SENSOR	Serviceable	325.60 FL	*- FL
5	1		*REAR BUMPER BEAM	Dented	938.49 FL	*938.49 FL
6	1		*EXHAUST PIPE CHROME	Serviceable	315.48 FL	*- FL
					Sub Total (S\$)	4,230.98 3,389.90
					- List Item Discount on L Items 10.00/10.00% (S\$)	423.10 338.99
					Total Parts (S\$)	3,807.88 3,050.91

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE REVERSE SENSOR & CHECK WIRING	New	80.00	50.00
2	TO REMOVE ,REPLACE REAR BUMPER ,REVERSE SENSOR & EXHAUST CHROME	New	600.00	380.00
3	TO SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (\$)			1,280.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >