

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010383/KPA3Q2**Date:** 06/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220088299
Claimant Vehicle No :	SLR8987M	Insured Vehicle No :	SMP4035K
Date of Loss:	15/10/2022	Nature of Claim:	TP
		Claim No:	3028291311SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8987M	Engine No:	2ZRS053713
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	ZVW518038653
Reg. Date:	30/08/2017 (Man. Year: 2017)	Odometer:	167486 km
Colour:	Metallic Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Roadstone 8 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Roadstone 8 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,816.92	1,133.42	683.50	37.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	520.00	740.00	58.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,076.92	1,653.42	1,423.50	46.26
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	3,076.92	1,300.00	1,776.92	57.75
+ GST 7.00/7.00% (S\$)	215.38	91.00	124.38	57.75
Nett Amount (S\$)	3,292.30	1,391.00	1,901.30	57.75
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,633.00		

INSPECTION

Date of Assignment:	19/10/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	19/10/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	2.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	488.50 FL	*488.50 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.60 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Cracked	112.60 FL	*112.60 FL
4	1		*REAR BUMPER LOWER GARNISH	Dented	576.80 FL	*576.80 FL
5	1		*REAR BUMPER TOWING COVER	Serviceable	54.80 FL	*- FL
6	1		*REAR BUMPER ANTENNA SENSOR	Serviceable	78.50 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Repair	336.20 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	Serviceable	155.90 FL	*- FL
9	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR TAILGATE OUTER GARNISH (NPA)	Repair	0.00 FL	*- FL
11	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
12	1		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
13	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,295.90	1,427.90
- List Item Discount on L Items 25.00/25.00% (\$)	478.98	294.48
Total Parts (\$)	1,816.92	1,133.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS	New	500.00	250.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	500.00	220.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	50.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	80.00	0.00
5	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	80.00	0.00
Gross Labour Cost (\$\$)			1,260.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >