

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22010384/UNY3Q2**Date:** 15/11/2022**REFERENCE**

Insured/Claimant:	MOH THAI TOW	Policy No:	DMPG22011320		
Date of Loss:	14/10/2022	Nature of Claim:	OD	Claim No:	CDMPG22002170

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SME4771B</b>	Engine No:	G4LDJD048102
Make & Model:	HYUNDAI I30, 1.6 (A)	Chassis No:	TMAH3513VJJ070828
Reg. Date:	29/09/2018 (Man. Year: 2018)	Odometer:	73539 km
Colour:	Grey		
Engine Capacity:	1353 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,725.10	6,531.10	3,194.00	32.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,020.00	980.00	49.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,725.10</b>	<b>7,551.10</b>	<b>4,174.00</b>	<b>35.60</b>
<b>- Excess (S\$)</b>	0.00	1,000.00	-1,000.00	
<b>(S\$)</b>	11,725.10	6,551.10	5,174.00	44.13
<b>+ GST 7.00/7.00% (S\$)</b>	820.76	458.58	362.18	44.13
<b>Nett Amount (S\$)</b>	<b>12,545.86</b>	<b>7,009.68</b>	<b>5,536.18</b>	<b>44.13</b>

**INSPECTION**

Date of Assignment:	19/10/2022	Present Location:	Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected:	31/10/2022	Inspected At:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2022)
<b>Parts:</b>	144	HYUNDAI I30 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME4771B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*BONNET</b> (WCP)	Dented	1,150.00 F	*1,150.00 F
2	10		<b>*BONNET INSULATOR CLIPS</b>	Not Necessary	40.00 FS	*- FS
3	1		<b>*FRONT BUMPER</b> (WCP)	Torn	700.00 F	*700.00 F
4	2		<b>*FRONT BUMPER SIDE RETAINER</b> (WCP)	Necessary	130.00 F	*130.00 F
5	10		<b>*FRONT BUMPER CLIPS</b>	Necessary	40.00 FS	*40.00 FS
6	1		<b>*FRONT BUMPER RIVET</b>	Necessary	4.00 FS	*4.00 FS
7	2		<b>*FRONT BUMPER BRACKET</b> (WCP)	Bent	90.00 F	*90.00 F
8	1		<b>*RADIATOR GRILLE</b> (WCP)	Cracked	425.00 F	*425.00 F
9	1		<b>*RADIATOR GRILLE CHROME MOULDING</b> (WCP)	Cracked	550.00 F	*550.00 F
10	1		<b>*RADIATOR GRILLE LOGO EMBLEM</b> (WCP)	Scratched	26.00 F	*26.00 F
11	1		<b>*RADIATOR GRILLE UPPER GARNISH</b> (WCP)	Cracked	95.00 F	*95.00 F
12	1		<b>*FRONT NUMBER PLATE</b>	Bent	45.00 FS	*40.00 FS
13	1		<b>*FRONT NUMBER PLATE BASE</b> (WCP)	Bent	45.00 F	*45.00 F
14	1		<b>*FRONT BUMPER CENTRE GRILLE</b> (WCP)	Not fitted	115.00 F	*- F
15	2		<b>*HEADLAMP</b> (WCP)	Cracked	1,800.00 F	*1,800.00 F
16	2		<b>*HEADLAMP LOWER BRACKET</b> (WCP)	Not Necessary	110.00 F	*- F
17	1		<b>*FRONT BUMPER SPONGE</b> (WCP)	Torn	195.00 F	*195.00 F
18	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Dented	515.00 F	*515.00 F
19	1		<b>*FRONT SUPPORT PANEL</b> (WCP)	Not Necessary	1,100.00 F	*- F
20	1		<b>*FRONT SUPPORT PANEL GARNISH</b> (WCP)	Not Necessary	175.00 F	*- F
21	10		<b>*FRONT SUPPORT PANEL GARNISH CLIPS</b>	Not Necessary	40.00 FS	*- FS
22	1		<b>*AIR-CON CONDENSER</b> (WCP)	Not Necessary	365.00 F	*- F
23	1		<b>*RADIATOR</b> (WCP)	Not Necessary	850.00 F	*- F
24	1		<b>*COOLANT</b>	Not Necessary	40.00 FS	*- FS
25	1		<b>*RADIATOR AIR GUIDE</b> (WCP)	N/S Twisted	150.00 F	*75.00 F
26	1		<b>*FRONT BUMPER TOP RUBBER SEAL</b> (WCP)	Necessary	65.00 F	*65.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>8,860.00</b>	<b>5,945.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	865.10	586.10

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>9,725.10</b>
						<b>6,531.10</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	VACCUM, RE-OIL AND RENEW AIR-CON GAS	New	150.00	0.00
3	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL, REPAIR INNER PANEL, REWELD INNER PANEL, REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	900.00	400.00
4	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	900.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,000.00</b>	<b>1,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >