



INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG22011320	Date of Loss:	14/10/2022
Vehicle Reg. No.:	SME4771B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MOH THAI TOW		
Driver:	MOH YONGJUN		
Make/Model:	HYUNDAI I30, 1.6 (A)	Vehicle Reg. Date:	29/09/2018
Vehicle Colour:	GREY		
Engine No:	G4LDJD048102	Chassis No:	TMAH3513VJJ070828
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

COST OF CLAIMS

	Amount
Parts	9,725.10
Miscellaneous Items	0.00
Labour	2,000.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	11,725.10
+ GST 7.00% (\$)	820.76
Nett Amount (\$)	12,545.86

This claim is handled by: **JOSHUA NG**

not authorized
31/10/22
P/P 4
take photo before party.
Excess \$1000
5 days

Generated using Merimen e-Claims Internet Estimation & Adjusting System

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Oct 2022)

Parts: 144 HYUNDAI I30 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SME4771B/19/10/2022 11:21

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>mm</i>	0.00	0.00	*1,150.00 F
2	10		*BONNET INSULATOR CLIPS <i>mm</i>	0	0.00	*40.00 FS X
3	1		*FRONT BUMPER <i>To-1</i>	0.00	0.00	*700.00 F
4	2		*FRONT BUMPER SIDE RETAINER <i>ner</i>	0.00	0.00	*130.00 F
5	10		*FRONT BUMPER CLIPS <i>ner</i>	0	0.00	*40.00 FS
6	1		*FRONT BUMPER RIVET <i>ner</i>	0	0.00	*4.00 FS
7	2		*FRONT BUMPER BRACKET <i>but</i>	0.00	0.00	*90.00 F
8	1		*RADIATOR GRILLE <i>one</i>	0.00	0.00	*425.00 F
9	1		*RADIATOR GRILLE CHROME MOULDING <i>one</i>	0.00	0.00	*550.00 F
10	1		*RADIATOR GRILLE LOGO EMBLEM <i>scr</i>	0.00	0.00	*26.00 F
11	1		*RADIATOR GRILLE UPPER GARNISH <i>one</i>	0.00	0.00	*95.00 F
12	1		*FRONT NUMBER PLATE <i>buy</i> <i>405/N</i>	0	0.00	*45.00 FS 40
13	1		*FRONT NUMBER PLATE BASE <i>but</i>	0.00	0.00	*45.00 F
14	1		*FRONT BUMPER CENTRE GRILLE <i>NR</i>	0.00	0.00	*115.00 F X
15	2		*HEADLAMP <i>one</i>	0.00	0.00	*1,800.00 F
16	2		*HEADLAMP LOWER BRACKET <i>mm</i>	0.00	0.00	*110.00 F X
17	1		*FRONT BUMPER SPONGE <i>To-1</i>	0.00	0.00	*195.00 F
18	1		*FRONT BUMPER REINFORCEMENT <i>mm</i>	0.00	0.00	*515.00 F
19	1		*FRONT SUPPORT PANEL <i>mm</i>	0.00	0.00	*1,100.00 F X
20	1		*FRONT SUPPORT PANEL GARNISH <i>mm</i>	0.00	0.00	*175.00 F X
21	10		*FRONT SUPPORT PANEL GARNISH CLIPS <i>11</i>	0	0.00	*40.00 FS X
22	1		*AIR-CON CONDENSER <i>mm</i>	0.00	0.00	*365.00 F X
23	1		*RADIATOR <i>mm</i>	0.00	0.00	*850.00 F X
24	1		*COOLANT <i>mm</i>	0	0.00	*40.00 FS X
25	2		*RADIATOR AIR GUIDE <i>mm</i> <i>151w1</i>	0.00	0.00	*150.00 F <i>tpc</i>
26	1		*FRONT BUMPER TOP RUBBER SEAL <i>ner</i>	0.00	0.00	*65.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	8,860.00
+ Margin on L,N Items 10.00% (\$\$)	865.10
Total Parts (\$\$)	9,725.10

Falcon-Air Auto Services Pte Ltd/SME4771B/19/10/2022 11:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK LIGHT AND WIRING	New	50.00
2	VACCUM, RE-OIL AND RENEW AIR-CON GAS	New	150.00
3	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL, REPAIR INNER PANEL, REWELD INNER PANEL, REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	900.00
4	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	900.00
Gross Labour Cost (\$\$)			2,000.00

Falcon-Air Auto Services Pte Ltd/SME4771B/19/10/2022 11:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD (a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

Pre Review done base on survey information provided
Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic
Amount : \$7551.10
Repair Duration: 5 days