

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC22010386/Tny3m4
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	11/11/2022
			Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	GBH 2104E	Veh. Inspected	PC 3091L
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VC05/026427	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	19/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JTFHT02P600154496	Colour	SILVER
	Odometer	243979 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/R15	HANKOOK	6 mm
	L/H Front Tyre	195/R15	HANKOOK	6 mm
	R/H Rear Tyre	195/R15	HANKOOK	6 mm
	L/H Rear Tyre	195/R15	HANKOOK	6 mm
4. Description of Damages				
	THE VEHICLE SUS	ICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
5. General Information				
	Accident Date	16/10/2022	Inspect Date / Time	19/10/2022 (01:00 PM)
	Survey held at	SHENG LI LAI		
		2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC22010386/Tny3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser