



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 2493K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	829.60	-
1	REAR RH SIDE BUMPER	NOT NECESSARY	48.18	-
1	REAR RH WHEEL ARCH	TO REPAIR SEE LABOUR	287.20	-
	LESS 20% DISCOUNT		-233.00	-
			931.98	-
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
			80.00	-
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR REMOVING REAR BUMPER, REAR RH SIDE BUMPER, REAR RH WHEEL ARCH OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR RH WHEEL ARCH.		800.00	200.00
	TO RESPRAY REAR BUMPER, REAR RH SIDE BUMPER, REAR RH WHEEL ARCH.		800.00	500.00
	TO DEACTIVE AND ACTIVE HIGH VOLTAGE HYBRID BATTERY AS SAFETY PRECAUTIONS.		300.00	30.00
	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS.	NOT NECESSARY	200.00	-
			2,100.00	730.00
GRAND TOTAL			3,111.98	730.00
RECOMMENDED COST OF REPAIRS				730.00

Report Ref No. CS/SPF22010388/Ewy3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$730-\$800

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.