MEF: CS/CT 220/0390/Tay3. ASSIGNMENT Veh No: 5MV 373/5 Yr Regn: 2020 1 Sept From: Date: Type: Mcar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: (CD) TP I WS I TP RES I OD RES I EVA I INV I MV Truck / Trailer or 1490. 1.5 To Inspect Vehicle No: Make: Insured / Std / NI / NA at Workshop m/s Colour T/Radio; Insured / Std / NI / NA Sp.Reading Eng/No: Insured: LSJ4244931N029240. C/No: Policy No. Gen. Cond: Good Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or \$3750 Excess: Sum Insured: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: Nil / S/Rim / STD A/Rim or Make of Veh: Tyre Size: (Policy Condition) BS / DUN / EXNOVA / GY /-FS / LIZA /MIC) OHTSU / PIR / SUMI / Remark: The veh had commenced its N/S OIS repair at the time of inspection. TOYO / YOKO or 912 OK. Rear Bal. or Market Value: Front R/Bal. R/Bal. Consistent?: Yes or No IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: D.O.A. Res.: Yes or No Est. Repairs: days 3 Val.: Yes or No SAT Lum Sum: Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA I REY I REP. I 24 HRS Rear N Vehicle: IN/OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction Date/Time, File Pass to? : Preli. Report Days Of Repair: : Final Report Resurvey No. of Trip: Survey Fee: Date/Time, File Return to? Transportation: Add Fee:

:Site Insp (\$

: Interview (\$

Tech. Invs (\$

Weellend (\$

Reperformat:

Lump Sum / LB.E. Ca

_S + RS.__SI

Photos

Others

TOTAL

SAT (SG) PTE LTD

61 Ubi Road 1 #04-14 Oxley Bizhub Singapore 408727 TEL: 6242 2212 FAX: 62426169

Vehicle No: SMV3731J Model No. M.G Chassis no. LSJA24

Accident Date: 08.09.2022 Owner: Yeo Quek Khim Date of Estimate: 16/09/2022

\$50.00 40.

Estimate for Accident Vehicle No. SMV3731J

	List Items:	Qty	Unit Price	Total Amount
1	Rear bumper upper	1	\$782.40	\$782.40 Ll
2	Rear bumper lower	1	\$498.00	\$498.00 de
3	Rear bumper lower spoiler	1	\$282.00	\$282.00 de/
4	Rear bumper reinforcement	1	\$580.00	\$580.00 7
5	Rear bumper side retainer	2 K		
6	Rear bumper clips (Set)	1	\$50.00	\$50.00 LH de/ \$50.00 Ne(/
7	Rear bumper reverse sensor	کهرا	\$348.00	
8	Rear end panel	1	\$154.00	\$1,392.00 m is
9	Rear fog lamp Ih	1	\$154.80	\$154.00 RA
10	Tailgate	1		\$154.80 Ona/
11	Tailgate lamp Ih	1	\$3,240.00	\$3,240.00 bt/
12	Tailgate logo	1	\$630.00	\$630.00 0~4/
13	Tailgate weatherstrip		\$45.00	\$45.00 Nec/
14	Tailgate inner trim	1,	\$125.00	\$125.00 🗶
15	Tailgate windscreen glass moulding	1	\$105.00	\$105.00 ⊀
16	Tailgate windscreen glass sealant	1	\$38.00	\$38.00 NOI
17	Taillamp Ih	1	\$27.00	\$27.00 Wal
18	•	1,	\$1,104.00	\$1,104.00 CMA
	Taillmap panel Ih	1	\$93.00	\$93.00 RY
19	Rear fender arch garnish	2	\$115.00	\$230.00 X
20	Rear exhaust silencer	1	\$2,640.00	\$2,640.00 7
21	Rear number plate	1	\$30.00	\$30.00 ×
		S	ub-Total Amount =	\$10,969.80
			Add 15%	\$1,645.47
			Sub-Total =	\$12,615.27

Labour charges

T	Panel beating for replace and repair affected parts	
2	Spray painting	\$1,400.00 700.
	Apply putty and anti-corrosion to affected parts.	\$1,500.00 750
4	Wiring / bulb checking	\$100.00 40

5	Transfer tailgate mechanisms			\$150.00 60
6	Remove & refix tailgate windscreen glass			\$200.00 120
7	Remove & refix rear bumper reverse sensor			\$100.00 50
8	Remove & refix rear exhaust silencer		_	\$280.00 100
			_	\$3,780.00
			-	
		Total parts	=	\$12,615.27
		Total labour	= _	\$3,780.00
		Total Amount	= _	\$16,395.27

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfilm 97495749

Not suchwise Ex \$3750

19/10/22 e 4pm.

6-7days.

tanfilm C (bhanto.wm