

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010392/RNY3Q2**Date:** 02/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00018502200

Claimant Vehicle No : SLQ8531A **Insured Vehicle No :** SND1605L

Date of Loss: 15/10/2022 Nature of Claim: TP Claim No: SNM22D207393/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ8531A**

Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B4532667

Reg. Date: 25/07/2017 (Man. Year: 2017) Chassis No: JHMRU1830GX202667

Colour: Black Odometer: 44710 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,192.41	1,858.66	2,333.75	55.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,970.00	6,775.00	5,195.00	43.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,162.41	8,633.66	7,528.75	46.58
+ GST 7.00/7.00% (S\$)	1,131.37	604.36	527.01	46.58
Nett Amount (S\$)	17,293.78	9,238.02	8,055.76	46.58

INSPECTION

Date of Assignment: 18/10/2022

Date Inspected: 31/10/2022 Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2022)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ8531A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE COMP	Bent	686.92 FS	*686.92 FS
2	1		*LOCK ASSYTAILGATE	Not Necessary	68.32 FS	*- FS
3	1		*WEATHERSTRIP TAILGATE	Not Necessary	79.20 FS	*- FS
4	1		*STOPPETAILGATE (2 PCS)	Necessary (1 PCS ONLY)	6.15 FS	*3.07 FS
5	1		*EMBLEMRR	Necessary	11.55 FS	*11.55 FS
6	1		*EMBLEMRR ,I-VTEC	Necessary	12.52 FS	*12.52 FS
7	1		*GLASS SET ,RR.WINDSHIELD	Not Necessary	554.85 FS	*- FS
8	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
9	1		*DAMPERSTD 5X5	Necessary	6.82 FS	*6.82 FS
10	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
11	1		*CAPPIVOT	Necessary	3.90 FS	*3.90 FS
12	1		*FASTENER BW/SHIELD (4 PCS)	Necessary	15.90 FS	*15.90 FS
13	2		*FASTENER B	Necessary	8.10 FS	*8.10 FS
14	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*5.70 FS
15	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
16	1		*LAMP UNITL	Not Necessary	382.20 FS	*- FS
17	1		*FACEL.RR BUMPER CORNER	Scratched	77.85 FS	*75.60 FS
18	1		*SPACER ,L RR.BPR S	Necessary	13.57 FS	*13.57 FS
19	1		*FACE ,RR.BUMPER	Torn	363.52 FS	*363.52 FS
20	1		*REFLECTOR ASSYL.RR	Scratched	135.30 FS	*135.30 FS
21	1		*CLIP BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
22	1		*PANEL COMPRR	Repair	299.55 FS	*- FS
23	1		*LINING ASSYRR.PANEL	Not Necessary	35.25 FS	*- FS
24	1		*BASE COMP ,L,TRUNK SIDE LINING	Not Necessary	109.05 FS	*- FS
25	1		*ACT RR SENSOR	Necessary	320.00 FS	*320.00 FS
26	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
27	1		*END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*BODY UNDERSIDE COATING	Not Necessary	350.00 FS	*- FS
29	1		*SOLAR FILM ON REAR WINDSCREEN	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,192.41** **1,858.66**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE RR.WINDSCREEN	New	650.00	650.00
2	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	280.00	180.00
3	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	650.00	650.00
4	RESET VEHICLE SMART ENTRY SYSTEM	New	600.00	500.00
5	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	600.00	500.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	325.00
7	REMOVE & RENEW REVERSE SENSORS	New	350.00	200.00
8	CUT OFF & RENEW RR PANEL STRAIGHTEN ALIGN	New	4,550.00	1,950.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,640.00	1,820.00
Gross Labour Cost (\$)			11,970.00	6,775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >