



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 87E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	GRAZED / CRACKED	1,225.00	1,225.00
1	FRONT BUMPER FOG LAMP RH	REFIT	223.00	-
1	SET HEADLAMP ASSY	O/S GRAZED / CUT	1,774.00	1,188.92
1	RHF QUARTER PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-322.20	-241.39
			2,899.80	2,172.53
	LABOUR			
	TO CHECK LIGHTINGS & WIRINGS.		50.00	30.00
	TO REPLACE DAMAGED PARTS / PANELS. CONDUCT CUTTING, WELDING, STRAIGHTENING, & PANEL BEATING ON AFFECTED AREA. RE-ALIGN ALL AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF RHF QUARTER PANEL.		800.00	400.00
	TO PUTTY, GRIND SMOOTHEN & RESPRAY REPLACEMENT & AFFECTED PANELS. (3 TONE WITH DESIGN).		1,000.00	200.00
	ANTI RUST ON AFFECTED PANELS.		100.00	40.00
			1,950.00	670.00
GRAND TOTAL			4,849.80	2,842.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS3/ASM21001010/Rqy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.