



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 5479P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BENT	1,350.00	1,350.00
1	REAR BUMPER LH BRACKET	TO REPAIR SEE LABOUR	380.00	-
1	REAR LH TAILLAMP	CRACKED	1,280.00	1,280.00
1	REAR LH END PANEL OUTER	TO REPAIR SEE LABOUR	2,650.00	-
	LESS 10% DISCOUNT		-	-263.00
			5,660.00	2,367.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE SENSOR (SN)	SHORTED	300.00	200.00
4	SEALANT (SN)	NOT NECESSARY	40.00	-
			340.00	200.00
	<b><u>LABOUR</u></b>			
	LABOUR TO REMOVE & REFIT REAR WINDSCREEN TO ASSIST REPAIR .	NOT NECESSARY	350.00	-
	LABOUR TO REMOVE & REFIT LH CHROME CASING TO ASSIST REPAIR.		100.00	50.00
	CHECK WIRING.		30.00	20.00
	LABOUR TO REMOVE & REFIT REAR SEATS & TRIMS ETC TO ASSIST REPAIR.	NOT NECESSARY	300.00	-
	APPLY ANTI RUST.	NOT NECESSARY	50.00	-
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR BUMPER LH BRACKET AND REAR LH END PANEL OUTER .		1,500.00	700.00
	SPRAY PAINTING.		1,400.00	900.00
			3,730.00	1,670.00
	<b>GRAND TOTAL</b>		<b>9,730.00</b>	<b>4,237.00</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			<b>3,350.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO22010402/Kvy3q2

A handwritten signature in black ink, appearing to read 'KSC'.

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.