

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010405/AVY3E2**Date:** 18/11/2022**REFERENCE**

Insured/Claimant: KIAN NGIAP SEWING MACHINE PTE LTD

Policy No: 2100456652-03

Date of Loss: 25/02/2020

Nature of Claim: OD

Claim No: 0481899421SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGW8889X**

Make & Model: AUDI A4 AVANT, 2.0 TFSI (A)

Engine No: CNC148417

Reg. Date: 17/03/2016 (Man. Year: 2015)

Chassis No: WAUZZZ8KXFA186234

Colour: Grey

Odometer: 0 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$101,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35 R19

Rear Tyre Size: 245/35 R19

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,121.00	10,061.60	5,059.40	33.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,042.00	11,137.00	6,905.00	38.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,163.00	21,198.60	11,964.40	36.08
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	32,363.00	20,398.60	11,964.40	36.97
+ GST 7.00/7.00% (S\$)	2,265.41	1,427.90	837.51	36.97
Nett Amount (S\$)	34,628.41	21,826.50	12,801.91	36.97

INSPECTION

Date of Assignment: 20/10/2022

Date Inspected: 20/10/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Dented	2,745.00 FS	*2,196.00 FS
2	1		*FRONT DOOR OUTER SEAL	Necessary	193.00 FS	*154.40 FS
3	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
4	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
5	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	84.00 FS	*- FS
6	1		*FRONT DOOR CATCH	Necessary	113.00 FS	*90.40 FS
7	1		*EXTERIOR MIRROR MOUNTING - RH	Damaged	1,259.00 FS	*1,007.20 FS
8	1		*MIRROR CAP - RH	Cut	538.00 FS	*400.00 FS
9	1		*TURN SIGNAL INDICATOR	Cut	94.00 FS	*75.04 FS
10	1		*MIRROR GLASS - RH	Not Necessary	1,563.00 FS	*- FS
11	1		*FRONT WINDOW SLOT SEAL - RH	Not Necessary	289.00 FS	*- FS
12	1		*TYRE PRESSURE DATA PLATE	Necessary	18.00 FS	*14.40 FS
13	1		*REAR DOOR - RH	Distorted	2,745.00 FS	*2,196.00 FS
14	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	79.00 FS	*- FS
15	1		*REAR DOOR OUTER SEAL - RH	Necessary	209.00 FS	*167.20 FS
16	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
17	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
18	1		*REAR DOOR CATCH	Necessary	113.00 FS	*90.40 FS
19	1		*RAR WINDOW WELL TRIM STRIP - RH	Not Necessary	279.00 FS	*- FS
20	1		*SIDE PANEL - RH	Punctured	2,549.00 FS	*2,039.20 FS
21	1		*SIDE WINDOW - RH	Necessary	444.00 FS	*354.80 FS
22	1		*REAR SIDE WINDOW TRIM STRIPS - RH	Necessary	307.00 FS	*245.20 FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
25	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
26	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
27	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
28	1		*SUNDRIES	Necessary	400.00 FS	*26.72 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	15,121.00	10,061.60
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	0.00
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	300.00
3	TO INSTALL 1/4 GLASS SOLAR FILM	New	200.00	200.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
6	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	560.00
7	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY	New	300.00	0.00
8	TO DISMANTLE REAR BUMPER, REAR LID, RHS REAR DOOR AND RHS FRONT DOOR. CUT OUT AND WELD RHS REAR FENDER. TO RENEW RHS REAR DOOR AND RHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,000.00	4,000.00
9	TO RESPRAY RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, RHS WING MIRROR COVER, DOOR HANDLE, RHS SILL PANEL, DOOR ENTRANCES, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,350.00	3,025.00
10	TO REINSTALL STICKER	New	60.00	60.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			18,042.00	11,137.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >