

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010409/GVCE2**Date:** 22/02/2023**REFERENCE**

Insured/Claimant:	CHENG WEE LEE	Policy No:	2100452170-06	
Date of Loss:	14/10/2022	Nature of Claim:	OD	Claim No: 5667216649SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCX6810C	Engine No:	CVN002216
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF47GA024373
Reg. Date:	23/02/2016 (Man. Year: 2015)	Odometer:	89935 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50Z R17	Rear Tyre Size:	225/50Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,760.00	6,286.08	15,473.92	71.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,452.00	7,392.00	17,060.00	69.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,212.00	13,678.08	32,533.92	70.40
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	45,612.00	13,078.08	32,533.92	71.33
+ GST 8.00/8.00% (S\$)	3,648.96	1,046.25	2,602.71	71.33
Nett Amount (S\$)	49,260.96	14,124.33	35,136.63	71.33

INSPECTION

Date of Assignment:	20/10/2022		
Date Inspected:	19/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER - RH	Dented	861.00 FS	*688.80 FS
2	1	*FRONT FENDER ATTACHMENTS PARTS	Not Necessary	225.00 FS	*- FS
3	1	*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	81.00 FS	*- FS
4	1	*FRONT FENDER BRACKET - RH	Not Necessary	41.00 FS	*- FS
5	1	*FRONT FENDER BRACE - RH	Not Necessary	132.00 FS	*- FS
6	1	*FRONT FENDER BRACKET FOR DEFORMATION ELEMENT - RH	Not Necessary	55.00 FS	*- FS
7	1	*FRONT FENDER BRACKET	Not Necessary	36.00 FS	*- FS
8	1	*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	37.00 FS	*- FS
9	1	*FRONT FENDER BRACKET	Not Necessary	37.00 FS	*- FS
10	1	*FRONT WHEEL HOUSING LINER	Not Necessary	262.00 FS	*- FS
11	1	*FRONT STONE CHIP GUARD	Necessary	57.00 FS	*45.28 FS
12	1	*FRONT COVER	Not Necessary	35.00 FS	*- FS
13	1	*FRONT COVER - RH	Not Necessary	26.00 FS	*- FS
14	1	*FRONT DOOR	Repair	3,431.00 FS	*- FS
15	1	*FRONT DOOR OUTER DOOR SEAL - RH	Not Necessary	229.00 FS	*- FS
16	1	*BONDING AGENT 30 ML	Not Necessary	51.00 FS	*- FS
17	1	*CLEANING SOLUTION 250 ML	Not Necessary	74.00 FS	*- FS
18	1	*FRONT DOOR ATTACHMENTS PARTS (NPA)	Not Necessary	0.00 FS	*- FS
19	1	*FRONT DOOR CATCH	Not Necessary	116.00 FS	*- FS
20	1	*EXTERIOR MIRROR MOUNTING	Cut	991.00 FS	*792.40 FS
21	1	*MIRROR CAP - RH	Not Necessary	308.00 FS	*- FS
22	1	*MIRROR GLASS - RH	Cut	1,757.00 FS	*1,405.60 FS
23	1	*FRONT TRIM PLATE FOR DOOR HANDLE	Not Necessary	98.00 FS	*- FS
24	1	*DATA PLATE FOR TYRE PRESSURE	Not Necessary	42.00 FS	*- FS
25	1	*REAR DOOR - RH	Buckled	3,431.00 FS	*2,744.80 FS
26	1	*REAR DOOR OUTER SEAL - RH	Necessary	229.00 FS	*182.80 FS
27	1	*BONDING AGENT	Necessary	51.00 FS	*40.56 FS
28	1	*CLEANING SOLUTION 250 ML	Necessary	74.00 FS	*58.96 FS
29	1	*APPLICATOR FRONT / REAR DOOR	Not Necessary	18.00 FS	*- FS
30	1	*SEALING STRIPS	Not Necessary	19.00 FS	*- FS
31	1	*REAR DOOR ATTACHMENTS PARTS	Not Necessary	943.00 FS	*- FS
32	1	*REAR DOOR CATCH	Not Necessary	134.00 FS	*- FS
33	1	*REAR DOOR TRIM PLATE FOR DOOR HANDLE - RH	Not Necessary	98.00 FS	*- FS
34	1	*REAR DOOR HANDLE HOUSING	Not Necessary	9.00 FS	*- FS
35	1	*REAR DOOR COVER - RH	Not Necessary	7.00 FS	*- FS
36	1	*MOUNTING BAR - RH	Not Necessary	183.00 FS	*- FS
37	1	*REAR DOOR WINDOW REGULATOR	Not Necessary	305.00 FS	*- FS
38	1	*SIDE PANEL FRAME - RH	Repair	3,199.00 FS	*- FS
39	2	*RIVETTED CAP NUT	Necessary	7.00 FS	*5.60 FS
40	10	*CLIPS	Necessary	9.00 FS	*7.20 FS
41	1	*WHEEL HOUSING LINERS - RH	Not Necessary	260.00 FS	*- FS
42	1	*REAR WINDSCREEN	Not Necessary	1,287.00 FS	*- FS
43	1	*REAR 1/4 GLASS	Not Necessary	685.00 FS	*- FS
44	2	*PRIMER	Not Necessary	44.00 FS	*- FS
45	2	*HINGE HALVES LOWER RH	Not Necessary	106.00 FS	*- FS
46	1	*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
47	1	*CAVITY WAX	Not Necessary	140.00 FS	*- FS
48	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
49	1	*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
50	1	*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
51	1	*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*RHS REAR RIM (NPA)	Not Necessary	0.00 FS	*- FS
53	1		*SUNDRIES	Necessary	600.00 FS	*134.08 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					21,760.00	6,286.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	700.00
3	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	280.00	0.00
4	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE RENEWAL OF LHS REAR FENDER	New	600.00	0.00
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	0.00
6	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	0.00
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGES AND RENEW WHERE NECESSARY	New	1,400.00	0.00
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
9	TO DISMANTLE AND REINSTALL FRONT BUMPER AND REAR BUMPER. TO RENEW RHS FRONT DOOR AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER AND RHS SILL PANEL. TO REPAIR RHS B-PILLAR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,500.00	3,000.00
10	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, RHS FRONT DOOR, DOOR HANDLES, RHS B-PILLAR, ROOF CHANNEL, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING	New	7,500.00	2,950.00
11	TO RENEW RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	0.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
13	TO RESPRAY RHS FRONT FENDER (Supplementary)	New	1,400.00	550.00
Gross Labour Cost (\$\$)			24,452.00	7,392.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >