

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 2305P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|----------------------------------|---------------|----------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | HOLDER | CRACKED | 320.00 | 320.00 |
| 1 | CHAIN OILER | SCRATCHED | 200.00 | 200.00 |
| 1 | DID 520 VX3 CHAIN | NOT NECESSARY | 150.00 | - |
| 1 | LEFT TAIL COVER | SCRATCHED | 120.00 | 120.00 |
| 1 | MAIN STAND | BENT | 280.00 | 280.00 |
| 1 | YUASA YTZ12S | NOT NECESSARY | 155.00 | - |
| | LESS 10% DISCOUNT | | - | -92.00 |
| | | | 1,225.00 | 828.00 |
| | <u>LABOUR</u> | | | |
| | TOWING MOTOR BIKE TOWING. } | | 50.00 | 60.00 |
| | TOWING MIKE MOTOR RECOVERY. } | | 45.00 | - |
| | LABOUR (FORK PRESS). | | 180.00 | 150.00 |
| | | | 275.00 | 210.00 |
| | GRAND TOTAL | | 1,500.00 | 1,038.00 |

| RECOMMENDED COST OF REPAIRS | | | 1,038.00 |
|-----------------------------|--|--|----------|
|-----------------------------|--|--|----------|

Report Ref No. CS3/ASM21000888/Rqy3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator