11/17/22, 4:17 PM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## **VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited Our File No: CS/ICS22010414/EWY3Q2

10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Date: 17/11/2022

**REFERENCE** 

Insured/Claimant: HOGBERG FRED RICKAD ROBIN WILLIAM Policy No: MPC22P00101800

Date of Loss: 16/09/2022 Nature of Claim: OD Claim No: DMPC2200467H/ST

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMQ8563X

Make & Model: BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A) Engine No: A5900678N20B20B

Reg. Date: 12/11/2014 (Man. Year: 2013) Chassis No: WBA5A32040D335236

Colour: White Odometer: 101809 km

Engine Capacity: 1997 cc
Market Value/New Car Price: \$\$63,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 245/45 R15 Rear Tyre Size: 245/45 R15
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS         | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts                  | 7,217.10   | 6,101.70   | 1,115.40   | 15.45  |
| Miscellaneous Items    | 35.00      | 35.00      | 0.00       | 0.00   |
| Labour                 | 1,100.00   | 750.00     | 350.00     | 31.82  |
| Paintwork Labour       | 600.00     | 250.00     | 350.00     | 58.33  |
| Towing                 | 0.00       | 0.00       | 0.00       |        |
| Gross Total (S\$)      | 8,952.10   | 7,136.70   | 1,815.40   | 20.28  |
| + GST 7.00/7.00% (S\$) | 626.65     | 499.57     | 127.08     | 20.28  |
| Nett Amount (S\$)      | 9,578.75   | 7,636.27   | 1,942.48   | 20.28  |

**INSPECTION** 

Date of Assignment: 20/10/2022 Present Location: Accord Auto Services Pte Ltd (HQ)

BLK 1009 BUKIT MERAH LANE 3

Date Inspected: 26/10/2022 Inspected At: #01-80

SINGAPORE 159723

Repairer: Accord Auto Services Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Nov 2022)

Parts: 143 BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMQ8563X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

| No.   | Qty    | Part No.  | Particulars   | Condition          | Repairer's | Amount      |
|-------|--------|-----------|---|--------------------|------------|-------------|
| 1     | 1      |           | *FRONT BUMPER   | Broken             | 1,680.00 F | *1,680.00 F |
| 2     | 1      |           | *FRONT LH BUMPER SIDE RETAINER *RH                        | Not Necessary      | 65.00 F    | *- F        |
| 3     | 1      |           | *FRONT BUMPER TOW COVER                                   | Not Necessary      | 80.00 F    | *- F        |
| 4     | 1      |           | *FRONT RH NUZZLE COVER                                    | Not Necessary      | 85.00 F    | *- F        |
| 5     | 1      |           | *FRONT RH FENDER  | Repair             | 720.00 F   | *- F        |
| 6     | 8      |           | *FRONT FENDER SHIELD RIVET                                | Not Necessary      | 24.00 F    | *- F        |
| 7     | 1      |           | *FRONT BUMPER SENSOR SEAL SET                             | Not Necessary      | 40.00 F    | *- F        |
| 8     | 1      |           | *FRONT RH HEADLAMP  | Broken             | 3,200.00 F | *3,200.00 F |
| Sup   | pleme  | entary #1 |   |                    |            |             |
| 9     | 1      |           | *FRONT RH COVER BOTTOM*Front Portion Of The Fender Shield | Broken             | 72.00 F    | *72.00 F    |
| 10    | 1      |           | *FRONT RH HEADLAMP LED MAIN LIGHT MODULE                  | Shorted            | 595.00 F   | *595.00 F   |
| F=Fra | nchise | part.     |   |                    | ,          |             |
|       |        |           |   | Sub Total (S\$)    | 6,561.00   | 5,547.00    |
|       |        |           | + Margin on L,N Items                                     | 10.00/10.00% (S\$) | 656.10     | 554.70      |
|       |        |           |   | Total Parts (S\$)  | 7,217.10   | 6,101.70    |
|       |        |           | Report was unsubmitted during this print-out.             |                    |            |             |

# Recommended Miscellaneous Items

| No Qty Particulars     | Repairer's | Amount |
|------------------------|------------|--------|
| Miscellaneous Items    |            |        |
| 1 1 FRONT BUMPER CLIPS | 35.00      | 35.00  |
| Sub Total (S           | \$) 35.00  | 35.00  |

#### Recommended Labour

| No          | Particulars   | Lab.Type         | Repairer's | Amount   |
|-------------|---|------------------|------------|----------|
| <u>Pair</u> | itwork Labour   |                  |            |          |
| 1           | Spray Painting to All Affected Areas  | New              | 600.00     | 250.00   |
| <u>Lab</u>  | our Items   |                  |            |          |
| 2           | Labour Remove / Refix Accident Damages Parts To Knock , Jack, Coweld and Realign Accident Affected Area | ut New           | 800.00     | 600.00   |
| 3           | Computer Diagnostic(Reset Necessary Electronic Function)  | New              | 300.00     | 150.00   |
|             | Gross I   | abour Cost (S\$) | 1,700.00   | 1,000.00 |
|             | Report was unsubmitted during   | this print-out.  |            |          |

< END OF ESTIMATES >