

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S2M049W0 Date: 13th Dec 2022

Our Ref: CS3/ASM22008486/Tcy3m4-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Khor Saw Theng

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFM 1232B INSURED VEHICLE: SHA 5048E

ACCIDENT DATE: 28/08/2022

We thank you for your instruction on 18/10/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFM 1232B from M/s Constant Appraiser Services.
- b) Singapore Accident Statement of Vehicles SFM 1232B and SHA 5048E.
- c) Final Repair Bill of SFM 1232B from M/s Tri King Auto Solutions Pte Ltd.
- d) Colour damaged vehicle photographs of SFM 1232B.

Pre-Repair Inspection Date: 31/08/2022 at M/s Tri King Auto Solutions Pte Ltd, 53 Ubi Avenue 1 #01-15 Paya Ubi Industrial Park, Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SFM 1232B

Make & Model : Mazda 3 4-Door Sedan 1.5L SP.6Eat

Year of Registration : 2014

Chassis Number : JM6BM42A8E0122374

Engine Capacity : 1496 cc

- 2. We recommend that the repairs of the entire damage require about <u>8 (Eight)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.