



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5276H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	COVER ,GUARD ,RR BUMPER LOWER (DISC 30%) (CONSISTENT)	MISSING	16.70	11.69
1	GUARD ,RR BUMPER LOWER (DISC 30%) (CONSISTENT)	SCRATCHED	623.50	436.45
1	SENSOR REVERSE (CONSISTENT)	NOT NECESSARY	180.00	-
1	ANTENNA ,ELECTRICAL KEY (CONSISTENT)	NOT NECESSARY	78.00	-
1	LENS & BODY ASSY ,RR BUMPER RH (CONSISTENT)	NOT NECESSARY	544.40	-
1	LENS & BODY ,REAR COMBINATION LAMP, RH (CONSISTENT)	NOT NECESSARY	489.00	-
1	COVER ,REAR FLOOR UNDER RH (CONSISTENT)	NOT NECESSARY	189.20	-
1	COVER ,REAR FLOOR UNDER CENTER (CONSISTENT)	NOT NECESSARY	249.10	-
1	PANEL SUB-ASSY ,FENDER REAR RH (CONSISTENT)	NOT NECESSARY	943.10	-
1	LINER ,REAR FENDER RH (CONSISTENT)	NOT NECESSARY	151.10	-
1	END PANEL SUB-ASSY ,BODY LOWER BACK (CONSISTENT)	NOT NECESSARY	707.10	-
1	PILLER ,RR BUMPER RH (CONSISTENT)	NOT NECESSARY	168.60	-
10	CLIPS PIECE ,FRT & RR BUMPER @\$4.80 (CONSISTENT)	NOT NECESSARY	48.00	-
1	SEAL RR BUMPER RH (CONSISTENT)	NOT NECESSARY	95.50	-
1	RETAINER ,RR BUMPER ,RH (CONSISTENT)	NOT NECESSARY	127.40	-
2	STOPPER ,RR BUMPER ,RH & LH (CONSISTENT)	NOT NECESSARY	4.80	-
2	SEAL ,RR BUMPER ARM ,RH & LH (CONSISTENT)	NOT NECESSARY	12.30	-
1	PAD ,RR BUMPER ,CTR (CONSISTENT)	NOT NECESSARY	2.50	-
2	PAD ,RR BUMPER ,RH & LH ,3 @\$4.30 (CONSISTENT)	NOT NECESSARY	8.60	-
2	PAD ,RR BUMPER ,RH & LH ,2 @\$4.30 (CONSISTENT)	NOT NECESSARY	8.60	-
2	PAD ,RR BUMPER ,RH & LH ,1 @\$4.30 (CONSISTENT)	NOT NECESSARY	8.60	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	360.10	-
1	COVER ,RR BUMPER ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	478.90	-
			5,495.10	448.14
	<b><u>LABOUR</u></b>			
	PANEL BEATING & BODY WORK .INCLUSIVE OF THE REPAIR OF COVER ,RR BUMPER ASSY .		676.00	200.00
	SPRAY PAINT.		1,116.00	200.00

Report Ref No. CC4/ASM22010417/Rpa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION .	NOT NECESSARY	120.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			2,292.00	400.00
<b>GRAND TOTAL</b>			<b>7,787.10</b>	<b>848.14</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>700.00</b>

Report Ref No. CC4/ASM22010417/Rpa3q2

**MOHAMMED RASUL BIN MOHD YUNUS**

**Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.