

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG22010423/UQY3E2  
**Date:** 18/11/2022

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001961318
<b>Claimant Vehicle No :</b>	GBL1606J	<b>Insured Vehicle No :</b>	SLM260E
Date of Loss:	19/10/2022	Nature of Claim:	TP
		Claim No:	288049

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBL1606J</b>	Engine No:	1KDB071998
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR (M)	Chassis No:	JTFHT02P900251658
Reg. Date:	24/03/2021 (Man. Year: 2021)	Odometer:	86113 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,232.50	1,318.75	8,913.75	87.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	1,570.00	2,600.00	62.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,402.50</b>	<b>2,888.75</b>	<b>11,513.75</b>	<b>79.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,402.50</b>	<b>2,300.00</b>	<b>12,102.50</b>	<b>84.03</b>

### INSPECTION

Date of Assignment:	21/10/2022	
Date Inspected:	20/10/2022	Inspected At: 2ND Auto Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre Singapore 417808
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2022)
<b>Parts:</b> 213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for GBL1606J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Repair	1,287.00 FL	*- FL
2	1		*REAR BUMPER BRACKET	Not Necessary	66.00 FL	*- FL
3	1		*REAR RIGHT SLIDING DOOR ASSY	Badly Dented	1,652.00 FL	*1,545.00 FL
4	1		*REAR RIGHT SLIDING DOOR LOCK	Not Necessary	289.00 FL	*- FL
5	1		*REAR RIGHT SLIDING DOOR LOWER HINGES	Not Necessary	218.00 FL	*- FL
6	1		*REAR RIGHT SLIDING DOOR OUTER HANDLE	Not Necessary	175.00 FL	*- FL
7	1		*REAR RIGHT SLIDING DOOR SENSOR	Not Necessary	292.00 FL	*- FL
8	1		*REAR RIGHT SLIDING DOOR RAILING	Not Necessary	279.00 FL	*- FL
9	1		*REAR RIGHT FENDER PANEL	Repair	4,850.00 FL	*- FL
10	1		*REAR RIGHT TAILLAMP	Not Necessary	885.00 FL	*- FL
11	1		*REAR RIGHT TAILLAMP LOWER PANEL	Not Necessary	209.00 FL	*- FL
12	1		*REAR RIGHT WHEEL HUB BEARING	Not Necessary	352.00 FL	*- FL
13	1		*REAR RIGHT SHOCK ABSORBER	Not Necessary	756.00 FL	*- FL
14	12		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
15	1		*REAR RIGHT SLIDING DOOR COMPANY STICKER	Not Necessary	350.00 FS	*- FS
16	1		*REAR RIGHT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
17	1		*REAR RIGHT WHEEL RIM COVER	Cut	250.00 FS	*120.00 FS
18	1		*REAR RIGHT WHEEL RIM	Not Necessary	650.00 FS	*- FS
19	1		*REAR MUDFLAP O/S	Torn	350.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,060.00</b>	<b>1,705.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	2,827.50	386.25
<b>Total Parts (\$)</b>	<b>10,232.50</b>	<b>1,318.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN ACCIDENT AFFECTED AREA AND REPLACE ACCIDENT DAMAGED PARTS	New	1,600.00	800.00
2	TO PUTTY AND SPRAY PAINTING ACCIDENT AFFECTED PORTION	New	1,600.00	600.00
3	TO CHECK REAR LIGHTING AND WIRINNG	New	50.00	20.00
4	TO APPLY ANTI RUST PROOFING TO ACCIDENT AFFECTED AREA	New	140.00	40.00
5	TO REMOVE AND INSTALL REAR RIGHT UNDERCARRIAGE PARTS	New	350.00	0.00
6	TO BALANCE REAR RIGHT WHEEL	New	50.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
8	TO REMOVE AND INSTALL REAR RIGHT SLIDING DOOR LOCK MECHANISM }	New	80.00	50.00
9	TO CHECK REAR RIGHT SLIDING DOOR CENTRAL LOCKING FOR FUNCTION }	New	80.00	0.00
10	TOWING SERVICE	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,170.00</b>	<b>1,570.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >