

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 27 Oct 2022

Preliminary Advice

Insured : SLM260E
Vehicle No
TP Vehicle No : GBL1606J
Make : TOYOTA HIACE
Date of Inspection : 20/10/2022
Inspection At : 2ND AUTO PTE LTD (HQ)
15 KAKI BUKIT ROAD 4, #01-05/53 BARTLEY BIZ CENTRE
SINGAPORE 417808

Accident Date : 19/10/2022
Assignment Date : 21/10/2022
Est. Duration of Repair : 5

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,402.50
Revised Amount	:S\$	2,888.75
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,888.75

Lump Sum Repair	:S\$	2,300.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

() The vehicle is economical for repair

() The vehicle is not economical for repair

() Part-by-Part repair

(X) Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.