

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/MSH22010423/Uqy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBL/606J
at Workshop m/s 2nd

of SLM2606

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

CBSTR

Vehicle: IN / OUT

Date: Person Contacted: LTA 24743

Veh No: GBL/606J Yr Regn: 24/03/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota hiace c.c 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 86113 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFHT02P900 25/658

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15 kopers

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/10/22 D.O.I. 20/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 24/10

L/S \$ 2300 Cred \$ 12102.50, 84%

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 5

1) Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: 1

Survey Fee:

2) Date/Time, File Return to?

Add Fee: : Site Insp (\$)

Transportation:

Report Format: MCR-TL

: Interview (\$)

Photos

: Tech. Invs (\$)

Others

Lump Sum / I.B.T. (\$ 2300)

: Weekend (\$)

TOTAL

GBL1606J Toyota Hiace

No	Qty	Parts Description	Parts Price
1	1	Rear bumper assy <i>1</i>	\$ 1,287.00 X
2	1	Rear bumper bracket <i>11</i>	\$ 66.00 X
3	1	Rear right sliding door assy <i>Body 1545</i>	\$ 1,652.00 /
4	1	Rear right sliding door lock <i>11</i>	\$ 289.00 X
5	1	Rear right sliding door lower hinges <i>11</i>	\$ 218.00 X
6	1	Rear right sliding door outer handle <i>11</i>	\$ 175.00 X
7	1	Rear right sliding door sensor <i>11</i>	\$ 292.00 X
8	1	Rear right sliding door railing <i>11</i>	\$ 279.00 X
9	1	Rear right fender panel <i>1</i>	\$ 4,850.00 X
10	1	Rear right taillamp <i>11</i>	\$ 885.00 X
11	1	Rear right taillamp lower panel <i>11</i>	\$ 209.00 X
12	1	Rear right wheel hub bearing <i>11</i>	\$ 352.00 X
13	1	Rear right shock absorber <i>11</i>	\$ 756.00 X
			<hr/>
			\$ 11,310.00
Less 25%			\$ 2,827.50
			<hr/>
			\$ 8,482.50

Special Nett Items

1	12	Rear bumper clips <i>11</i>	\$ 50.00 X
2	1	Rear right sliding door company sticker <i>11</i>	\$ 350.00 X
3	1	Rear right fender sealant <i>11</i>	\$ 100.00 X
4	1	Rear right wheel rim cover <i>11</i>	\$ 250.00 120
5	1	Rear right wheel rim <i>11</i>	\$ 650.00 X
6	1	Rear <i>mudflap 25</i> <i>7.11</i>	\$ 350.00 40
			<hr/>
			\$ 1,750.00

Total parts

\$ 10,232.50

*not Authorized
 del
 1/3 \$ 2300
 20/10/22 5 days*

GBL1606J Toyota Hiace

No	Description	Labour Charges
----	-------------	----------------

1	Labour for panel beating, cut, weld, straighten accident affected area and replace accident damaged parts.	\$ 1,600.00	800
2	To putty and spray painting accident affected portion.	\$ 1,600.00	600
3	To check rear lighting and wiring.	\$ 50.00	20
4	To apply anti rust proofing to accident affected area.	\$ 140.00	40
5	To remove and install rear right undercarriage parts.	\$ 350.00	X
6	To balance rear right wheel.	\$ 50.00	X
7	To conduct wheel alignment.	\$ 120.00	60
8	To remove and install rear right sliding door lock mechanism.	\$ 80.00	} 50
9	To check rear right sliding door central locking for function.	\$ 80.00	
10	Towing service.	\$ 100.00	X
Total labour :		\$ 4,170.00	

Total parts : \$ 10,232.50

Total labour : \$ 4,170.00

Total repair cost : \$ 14,402.50

2- 1545
 252
 1158.75
 160
 1570
 2888.75
 202
 2311

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: