

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22010427/EQY3Q2**Date:** 21/02/2023**REFERENCE**

Insured/Claimant: PANG CHEE WEE Policy No: DMPCNA00064952202

Date of Loss: 29/09/2022 Nature of Claim: OD Claim No: SNM22D206992/C01/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMP3922G**

Make & Model: MERCEDES-BENZ C180, 1.5 (A)

Engine No: 27491031651203

Reg. Date: 25/09/2019 (Man. Year: 2018)

Chassis No: WDD2050402R475730

Colour: Black

Odometer: 42191 km

Engine Capacity: 1595 cc

Market Value/New Car Price: S\$161,000.00

Price:

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,151.91	7,210.21	4,941.70	40.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,540.00	8,520.00	7,020.00	45.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,691.91	15,730.21	11,961.70	43.20
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	27,191.91	15,230.21	11,961.70	43.99
+ GST 8.00/8.00% (\$\$)	2,175.35	1,218.42	956.93	43.99
Nett Amount (\$\$)	29,367.26	16,448.63	12,918.63	43.99

INSPECTION

Date of Assignment: 20/10/2022

Date Inspected: 20/10/2022 Inspected At:

188 PANDAN LOOP SINGAPORE

Repairer: Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	143	MERCEDES-BENZ C180 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP3922G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,777.00 FS	*2,777.00 FS
2	2		*BOOT LID RETAINER WEDGE	Necessary	32.68 FS	*32.68 FS
3	2		*BOOT LID RETAINER WEDGE	Necessary	26.38 FS	*26.38 FS
4	1		*HOLE PLUG	Necessary	4.52 FS	*4.52 FS
5	1		*HOLE PLUG	Necessary	4.52 FS	*4.52 FS
6	2		*HOLE PLUG	Necessary	9.04 FS	*9.04 FS
7	1		*BOOT LID W/STRIP	Crushed	213.52 FS	*213.52 FS
8	1		*BOOT LID CHROME TRIM STRIP	Necessary	183.46 FS	*183.46 FS
9	1		*BOOT LID LOCK	Not Necessary	303.24 FS	*- FS
10	1		*BOOT LID SERVO LOCK STRIKER	Not Necessary	490.66 FS	*- FS
11	1		*BOOT LID LOCK GEAR MOTOR	Not Necessary	485.66 FS	*- FS
12	1		*BOOT LID C180 MODEL PLATE	Necessary	132.57 FS	*132.57 FS
13	1		*BOOT LID MERCEDES STAR	Necessary	52.05 FS	*52.05 FS
14	3		*SEALING GROMMET	Necessary	7.17 FS	*7.17 FS
15	1		*RIGHT REAR LAMP COMBINATION	Broken	785.92 FS	*785.92 FS
16	1		*RIGHT REAR GASKET FOR LIGHT HOUSING	Not Necessary	22.30 FS	*- FS
17	1		*REAR BUMPER	Dented	1,947.67 FS	*1,947.67 FS
18	1		*REAR BUMPER LOWER	Cut	370.69 FS	*370.69 FS
19	1		*REAR BUMPER LOWER CHROME TRIM STRIP	Necessary	310.34 FS	*310.34 FS
20	1		*RIGHT REAR BASIC MOUNTING FOR BUMPER	Broken	45.86 FS	*45.86 FS
21	1		*RIGHT REAR BASIC MOUNTING FOR BUMPER	Not Necessary	70.21 FS	*- FS
22	1		*REAR BASIC MOUNTING FOR BUMPER	Not Necessary	113.94 FS	*- FS
23	1		*REAR CROSS MEMBER	Not Necessary	772.94 FS	*- FS
24	1		*RIGHT REAR FENDER COVERING	Broken	50.89 FS	*50.89 FS
25	1		*REAR END PANEL TRIM GARNISH	Not Necessary	168.28 FS	*- FS
26	1		*REAR END PANEL	Not Necessary	1,655.71 FS	*- FS
27	1		*TS TWO -COMPONENT ADHESIVE	Not Necessary	858.76 FS	*- FS
28	1		*UNDERBODY PROTECTION WAX	Necessary	116.39 FS	*116.39 FS
29	1		*SEAM SEAL	Necessary	116.42 FS	*116.42 FS
30	4		*NUT	Necessary	23.12 FS	*23.12 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **12,151.91** **7,210.21**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS ,REMOVE AND REOLACE WITH NEW BODY PANELS WITH REFINISH	New	4,800.00	2,880.00
2	RESPRAY BOOT LID ,RIGHT REAR FENDER ,LEFT REAR FENDER ,REAR BUMPER AND REAR END PANEL	New	4,800.00	4,000.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS ,RESET SYSTEM TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
5	PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMENT	New	1,000.00	0.00
6	REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS	New	2,400.00	0.00
7	INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT	New	540.00	0.00
8	REMOVE AND REFIT REAR UPHOLSTERY ,TRIMS GARNISHS ,TRIMS BOARDS AND SEATS CUSHIONS FOR NEC.REPAIRS	New	1,200.00	960.00
9	APPLY CAVITY WAX ON AFFECTED AREAS	New	180.00	180.00
10	TO APPLY SEAL SEAM ON PANEL JOINTS	New	120.00	0.00
Gross Labour Cost (\$\$)			15,540.00	8,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >