



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|--|------------|
| MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581 | | Ref: CS/FCI22010428/Ucy3e2 Date: 04/11/2022 Code: FCI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | GZ 3385A | Veh. Inspected | GBF 8354X |
| Policy No. | D-22099996MCVP | Coverage (\$) | 0.00 |
| Claim No. | D22003251MCVP | Excess (\$) | 0.00 |
| Assign From | CAROLINE CABRERA | Assign Date | 20/10/2022 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA HIACE (M) | c.c | 2982 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | KDH2010194934 | Colour | RED |
| Odometer | 185386 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195 R15 | AUSTONE | 6 mm |
| L/H Front Tyre | 195 R15 | AUSTONE | 6 mm |
| R/H Rear Tyre | 195 R15 | AUSTONE | 6 mm |
| L/H Rear Tyre | 195 R15 | AUSTONE | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 11/10/2022 | Inspection Date | 20/10/2022 |
| Survey held at | LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | |