

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22010432/RPA3Q2**Date:** 20/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800045324
Claimant Vehicle No :	SG1696Z	Insured Vehicle No :	SLZ6392A
Date of Loss:	12/10/2022	Nature of Claim:	TP
		Claim No:	2636820093SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG1696Z		
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A)	Engine No:	902926C1097794
Reg. Date:	11/02/2016 (Man. Year: 2015)	Chassis No:	WEB62808323129413
Colour:	Multi-colour	Odometer:	597792 km
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8/8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,532.93	8,282.45	4,250.48	33.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,198.00	2,298.00	900.00	28.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,730.93	10,580.45	5,150.48	32.74
Approved Total (Overridden) (\$\$)		8,900.00		
Nett Amount (\$\$)	15,730.93	8,900.00	6,830.93	43.42
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	17/10/2022	
Date Inspected:	17/10/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRONT,CENTRE,FOR MB CITARO O530	Deformed	1,663.80 F	*1,663.80 FL
2	1		*FLAP :FRONT ,CENTRE ,FOR MB CITARO O530	Repair	1,513.05 F	*- FL
3	1		*COVERING;W/SCREEN EDGE BOTTOM (CITARO)	Repair	545.10 F	*- FL
4	1		*BUMPER FRONT ,LH .FOR CITARO O530	Cracked	1,767.78 F	*1,767.78 FL
5	1		*LAMP,BLINKER:FRONT,LEFT,FOR MB OC 500LE	Broken	155.30 F	*155.30 FL
6	1		*HEADLAMP FOR MERCEDES OC500 LE,LEFT	Not Necessary	1,276.50 F	*- FL
7	1		*FASTENER :FRT BUMPER ,FOR MB CITARO BUS	Necessary	19.35 F	*19.35 FL
8	1		*FASTENER :FRT BUMPER ,FOR MB CITARO BUS	Necessary	64.20 F	*64.20 FL
9	1		*BRACKET :LH,FRT BUMPER ,FOG MB CITARO BUS	Not Necessary	75.00 F	*- FL
10	1		*ACTIVATOR	Necessary	80.00 FS	*80.00 FS
11	10		*SEALANT SIKAFLEX	Necessary	370.00 FS	*370.00 FS
12	1		*PRIMER (SIKA 206 G+P)	Necessary	80.00 FS	*80.00 FS
13	1		*IU BRACKET	Necessary	35.00 FS	*35.00 FS
14	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS
15	1		*FRONT NUMBER PLATE	Bent	75.00 FS	*75.00 FS
16	1		*DOOR PROFILE	Cut	850.00 F	*850.00 FL
17	1		*WINDSCREEN :FRONT ,FOR MB CITARO O530	Cracked	3,887.85 F	*3,887.85 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	12,532.93 9,123.28
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 840.83
					Total Parts (\$\$)	12,532.93 8,282.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	2,120.00	1,590.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	878.00	708.00
3	TOWING CHARGE	New	200.00	0.00
Gross Labour Cost (\$\$)			3,198.00	2,298.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >