

(08/11/13) wef

ASS. REC. BY: Ref

REF:

2920

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SG 16962at Workshop m/s SMRTof 60, Mercedes Ind PK 64Insured: AIC

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SG 16962Yr Regn: 2016 196BType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ C140 6.4L c.c 6374Colour: MULTI

A/C: Insured / Std / NI / NA

Sp. Reading: 597792

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WGB 62808323129473Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8/8 mmL/Bal. 8 mmL/Bal. 8/8 mmD.O.A. 12/10/22D.O.I. 17/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 15/10/2022

User ID : GohKK2

Section A - Accident Details

Registration Number	SG1696Z
Case Reference Number	BUS/10/22/7012
Registration Date	11/2/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	CITARO O530
Name of Driver	Wang Ke
Type of Accident	Side Swipe
Accident Date and Time	12/10/2022 2:14 PM
Accident Reported Date and Time	14/10/2022 5:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1696Z - left front portion SLG6392A (TP) - INSURED WITH AIG
Prepared Date and Time	15/10/2022 9:08 AM
Chassis Number	WEB62808323129413
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$8,512.53	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$11,710.53	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	15/10/2022 9:23 AM	
Signature		X
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 15/10/2022
User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	1590
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$878.00	708
Total Spray Painting & Panel Beating	\$878.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	? receipt
Total Other Costs	\$200.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	na /
4006314			SEALANT SIKAFLEX	10.00	\$37.00	0.00	\$370.00		na /
4006313	CONSUMABLE	SIKA Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	na /
600917			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	na /
6009901	Body	6283850401	BUMPER:FRONT,CENT RE, FOR MB CITARO O530	1.00	\$1,663.80	10.00	\$1,497.42	Replace	de /
6009904	Body	6288850526	FLAP:FRONT,CENTRE,F OR MB CITARO O530	1.00	\$1,513.05	10.00	\$1,361.75	Replace	repar /
6010399			COVERING :W/SCREEN EDGE,BOTTOM (CITARO)	1.00	\$545.10	0.00	\$545.10	Replace	repar /
6009902	BODY LH	6288800172	BUMPER:FRONT,LH,FO R MB CITARO O530	1.00	\$1,767.78	10.00	\$1,591.00	Replace	com /
6009700	VE		LAMP,BLINKER:FRONT, LEFT, FOR MB OC 500 LE	1.00	\$155.30	10.00	\$139.77	Replace	bro /
6009509	VE		HEADLAMP FOR MERCEDES OC500 LE, LEFT	1.00	\$1,276.50	10.00	\$1,148.85	Replace	3 X
6010191	VM	9417500184	FASTENER:FRT BUMPER, FOR MB CITARO BUS	1.00	\$19.35	10.00	\$17.42	Replace	na /
6010190	VM	9437500084	FASTENER:FRT BUMPER, FOR MB CITARO BUS	1.00	\$64.20	10.00	\$57.78	Replace	na /
6010183	VM	6288802314	BRACKET:LH,FRT BUMPER, FOR MB CITARO BUS	1.00	\$75.00	10.00	\$67.50	Replace	3 X
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	na /
			FRONT NUMBER PLATE	1.00	\$75.00	0.00	\$75.00	Replace	na /
Total					\$7,462.08		\$7,141.59		bt /

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: